

FIRST RE-ESTABLISHMENT

GCDB 540100

Quarter corner common to Section 35, Township 32 South, Range 4 East and Section 2, Township 33 South, Range 4 East, W.M. $V = 20\frac{3}{4}^\circ$

Found the single original bearing tree, marked by R. Moore n 1884,

- A White Fir, now 42-inch diameter containing scribe marks, including "4" in partly opened upper face.

From the preceding original evidence, I set a 1x36-inch Galvanized iron pipe, 27 inches in the ground with a 2½-inch diameter bronze disc marked:

JACKSON COUNTY 1980
T32S R4E
35
¼S —
2
T33S

For the corner.

From which:

- The above-described original bearing tree bears Record: $S51^\circ W$, 20.46 feet to scribed face.

Original stone not found.

Marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- White Fir, 7-inch diameter bears $S35^\circ 52'E$, 36.20 feet.
- White Fir, 6-inch diameter bears $N41^\circ 00'W$, 80.34 feet.

Corner lies in old landing about 230 feet South of location marker, on 16-inch diameter Fir, alongside road.

October 21, 1980

R. Frost

Witness

T. Connolly

T. Newcomb USFS

Edward McGinty

County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 540100

Quarter corner common to Section 35, Township 32 South and Section 2, Township 33 South, Range 4 East, W.M.

Found at the corner position, exposed 6 ins. in a small mound of stones, the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on 1st Re-establishment in 1980, marked:

JACKSON COUNTY 1980

T32S R4E

32

¼S—

5

T33S

Single remaining original bearing tree recorded by R. Moore of the GLO in 1884,

- W. Fir, now 48 ins. diam. with a chopped-out weathered blaze, brs. S 51° W, 21.8 ft. to center at base. Record; 20.5 ft. to face.

Bearing trees recorded on said 1st Re-establishment, found with healed double blazes and measured to center at lower blaze:

- W. Fir, now 13 ins. diam. brs. record; S 35¾° E, 36.2 ft.
- W. Fir, now 16 ins. diam. brs. record; N 41° W, 80.3 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- P. Pine 5 ins. diam. brs. N 7½° E, 26.3 ft.

Corner lies approx. 230 ft. South of tag on a 20 Ins. diam. Fir on South side of gravel spur road.

June 27, 2011

H. Durkee

Kerry Bradshaw

Jackson County Surveyor

P. – 103

V. – 17°05'