

FIRST RE-ESTABLISHMENT

GCDB 100200

Section corner common to Section 30 and 31, Township 34 South, Range 1 West, and Section 25 and 36, Township 34 South, Range 2 West, W.M. $\angle = 19^\circ$

From the following evidence, at the location described below, I set a 1x36-inch G.I. pipe, 30 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1978

T34S	
25	30

36	31
R2W	R1W

Original bearing trees recorded by Ives and Hyde in 1854, found as follows:

- A burned, partial fir stump shell, about 36 inches diameter bears Record: $N61^\circ E$, 46.86 feet on slope, to estimated face.
- White Oak stump remains, containing old axe work, bears Record: $S25^\circ E$, 20.04 feet to estimated face.
- White Oak stob, 11-inch diameter, containing burned face and reverse impression of chain notch, bears Record: $S17^\circ W$, 39.60 feet on slope, to (reverse) chain notch.
- NW BT now gone.

I mark new trees CS BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 14-inch diameter, bears $N17\frac{1}{4}^\circ E$, 37.29 feet.
- Ponderosa Pine, 15-inch diameter, bears $S72^\circ E$, 16.94 feet.
- White Oak, 12-inch diameter, bears $S43\frac{3}{4}^\circ W$, 115.95 feet.
- Ponderosa Pine, 10-inch diameter, bears $N73^\circ W$, 18.56 feet.

Corner lies on SW slope, about 27 feet East of (down) N-S fence line.

March 29, 1978

B. Malotte

R. Frost

Approved by: Edward McGinty
County Surveyor