

FIRST RE-ESTABLISHMENT

GCDB 140500

Quarter corner to Sections 7 and 18, Township 34 South, Range 1 West.

Found original BT to SW dead, plainly scribed,

From which

- Set 1"x 36" galvanized pipe in mound of stone on west slope of draw on solid rock,

From which:

- A 10" White Oak scribed C.S.-BT bears N.75°W. 32.0 feet.
- A 12" White Oak scribed C.S.-BT bears S.09°15'W., 172.3 feet.

March 19, 1931
C. Z. Boyden,
Deputy County Surveyor

Tice & Pettegrew, Chainmen

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 140500

Quarter corner common to Sections 7 and 18, Township 34 south, Range 1 West, W.M.

Found the 1" galvanized iron pipe in a mound of stone as set for corner on the First Re-establishment by Deputy County Surveyor, C. Z. Boyden on March 19, 1931.

Replaced said pipe with a 1"x 36" galvanized iron pipe with a 2½" bronze cap stamped:

T34S R1W
7
¼S — Cor.
18
C.S.
1972

Set in a mound of stone.

From said pipe corner,

- The First Re-establishment bearing tree (now a 12" White Oak with healed blazes) bears S9½°W, 171.9 feet to the center (Record: S9¼°W, 172.3 feet);
- The First Re-establishment bearing tree (now a 12" White Oak snag, with scribe marks visible) bears N75°W, 32.0 feet to the face of the lower blaze. (Record: N75°W, 32.0 feet).

Mark a new tree as follows:

- Scribed an 8" White Oak, "CS-BT" which bears S68°E, 84.3 feet to the face of the lower blaze.

June 2, 1972
Lloyd Shreeve
Ray Webber

Approved By:
Mark E. Boyden
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 140500

Quarter corner common to Sections 7 and 18, Township 34 South, Range 1 West, W.M.

At the corner, found out of ground and downhill on rocky slide area, the 1x36-inch Galvanized iron pipe set on Second Re-establishment.

From the following evidence, reset at the corner position, the 2½ ins. brass cap (removed from the 1x36-inch Galvanized iron pipe) in concrete, set in a chipped out and cleaned rock crevice, said cap marked:

T34S R1W
7
—
¼ 18 Cor.
C.S.
1972

From which:

- Remains of the original bearing tree, a 12-inch White Oak shell, the portion with scribing barely discernable was found at base of shell, bears record N75°W, 32.0 feet to estimated face.
- Remains of the original bearing tree, a Manzanita, broken up and scattered, found piece with old axe work and scribing barely discernable, position unknown.
- The 12-inch White Oak, now 15 inches, taken on First Re-establishment Page 1, 1931, bears S8½°W, 171.9 feet. Record: S9½°W.
- The 11 ins. White Oak, taken on Second Re-establishment, Page 25, 1972, bears S68°E, 84.6 feet to center of tree at lower blaze, record 84.3 feet.
- A large flat rock, 3½ feet x 4 feet x 9 ins. thick, lies immediately southwesterly and adjacent to the corner.
- A down and rambling split rail fence bears North 25 feet. ±.
- The center of a creek in a deep draw bears East 70 feet. ±, c. south.

Corner lies on a loose, rocky East slope, approximately 225 feet West of road to `Lazy B` Ranch.

April 13, 1981
J. Swanson
R. Templin

Edward McGinty
County Surveyor

V = 18½°
P. - 61

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 140500

Quarter corner common to Sections 7 and 18, Township 34 South, Range 1 West, W.M.

Brass cap set in 1980 is now gone. Found a $\frac{1}{2}$ ins. depression with remains of rock tight around it on a large stone $4\frac{1}{2}$ feet x 4 feet x 12 inches.

Removed large stone and at corner set in a drill hole 4 ins. deep in bedrock a $\frac{5}{8}$ x 12 ins. rebar and over it a 1x15-inch Galvanized iron pipe with a 2 $\frac{1}{2}$ -inch diameter brass cap marked:

T34S R1W
7
 $\frac{1}{4}$ S —
18
C.S.
1992

Bearing trees found and described on Third Re-establishment, in 1980 found with healed blazes and measured to center of tree at lower blaze:

- White Oak, 13-inch diameter, bears $S69\frac{1}{2}^{\circ}E$, 84.60 feet. Record: $S68^{\circ}E$.
- White Oak, 14-inch diameter, bears Record: $S8\frac{1}{2}^{\circ}W$ 171.90 feet.

Set new references; P-K nail (2 ins. long) in drill hole with rock tight:

- Bears $N22\frac{3}{4}^{\circ}E$, 19.34 feet.
- Bears $N40^{\circ}W$, 20.31 feet.

Corner lies in large rocky opening and steep east slope.

April 10, 1992
T. Newcomb, Tech.
H. Durkee, Tech.

Verlyn Thomas
County Surveyor

V = $17\frac{1}{2}^{\circ}$

P.-18