

FIRST RE-ESTABLISHMENT

GCDB 240300

Quarter corner to Sections 20 & 29, Township 34 South, Range 1 West.

- Found 12" black oak to northwest with old axe mark; it appears that the scribe was previously cut out.
- Found stump hole with remains of fir roots to southeast,
- Also black oak easterly with old blaze with 81 growth rings over the old blaze.

From which evidence,

- Set a 4" x 12" x 18" rock for corner.

From which:

- A 12" black oak scribed C.S.-BT bears S.10°E., 52.2 feet.
- Scribed a 6" black oak C.S.-BT which bears N.25°W. 25.5 feet.

August 2, 1944

C. Z. Boyden

R. S. Watson

B. L. Campbell

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 240300

One-Quarter corner common to Sections 20 and 29, Twp. 34 South, Range 1 West, W.M.
 $V = 19\frac{1}{2}^\circ$

Found alongside the metal post (set in concrete) corner of South and West bearing fence lines, the $\frac{3}{4}$ -inch diameter smooth iron pin set on survey No. 3742 in 1968, with the 4x12x18 ins. stone noted on First Re-establishment (page 2) in 1940, marked with "X" on top and lying alongside corner.

Over found pin I set a 1x36-inch G.I. pipe 30 ins. in the ground, with a 2 $\frac{1}{2}$ -inch bronze disc. marked:

JACKSON COUNTY 1979
T34S R1W
20
 $\frac{1}{4}$ S —
29

- A Black Oak stob, 16-inch diameter, with axed out face, noted on First Re-establishment and implied to be the original Northwest BT marked by Ives and Hyde in 1854, bears N17°W, 61.1 feet to estimated face. Record (1854): N20°W, 62.04 feet.
- Bearing trees marked on First Re-establishment are now gone.

I mark new trees CS BT and take measurements to center of trees at lower blaze:

- Black Oak, 13-inch diameter, bears N74 $\frac{1}{2}$ °E, 34.34 feet.
- Black Oak, 6-inch diameter, bears N9 $\frac{1}{2}$ °W, 48.05 feet.

April 6, 1979
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor