

## FIRST RE-ESTABLISHMENT

GCDB 300100

Southwest corner of Section 33, Township 34 South, Range 1 West.

Found stumps of original bearing trees in Section 32, 33 and 5.

Set corner from which:

- A 10" Yellow Pine bears N.17½°E., 60.03 feet.
- An 8" White Oak bears S.34°W., 12.05 feet.

April 27, 1917  
A. T. Brown,  
County Surveyor  
H. L. Speck, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 300100

Section Corner on Twp. line - Sections 32 & 33, T34S, R1W and Sections 4 & 5, T35S, R1W.

Found stake in mound of stone at corner, together with the bearing trees described by Surveyor Brown as re-established April 27, 1917; also found remains of tree to northeast which correspond to original bearing tree.

Set a 2" x 31" iron pipe 32" in the ground, together with a mound of stone, for corner.

As the corner and old bearing trees are subject to overflow of Rogue River, I established new trees as follows:

- Scribed a 24" black oak, C.S.-BT which bears  $N49\frac{1}{4}^{\circ}W$ , 195.0 feet.
- Scribed a 5" white oak C.S.-BT which bears  $S84\frac{3}{4}^{\circ}W$ , 97.4 feet. (West 58 feet to foot of east slope in a small rocky draw).

C. I. Bourne  
W. R. Young

January 3, 1942  
C. Z. Boyden

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT


### THIRD RE-ESTABLISHMENT

#### GCDB 300100

Section corner common to Sections 32 and 33, Township 34 South, Range 1 West, and Sections 4 and 5, Township 35 South, Range 1 West, W.M.

Found 6 ins. deep the 2-inch diameter iron pipe set on Second Re-establishment, Township 35 South, Range 1 West, page 15 in 1942.

Set 3-inch diameter brass cap, in cement, in the top of found pipe, marked:



Bearing tree marked in 1942:

- A White Oak, now 7-inch diameter, with healed blazes, bears  $S84\frac{3}{4}^{\circ}W$ , 97.58 feet to center. Record: 97.4 feet.

Bearing tree recorded on First Re-establishment, T34S R1W, page 3 in 1917,:

- A White Oak, now 13-inch diameter, with healed blazes, bears Record:  $S34^{\circ}W$ , 12.05 feet to center of tree.

Mark new trees "C.S." - "BT" and take measurements to center of tree at lower blaze:

- White Oak, 5-inch diameter, bears  $N48\frac{1}{2}^{\circ}E$ , 78.34 feet.
- Ponderosa Pine, 13-inch diameter, bears  $S23^{\circ}E$ , 66.93 feet.
- White Oak, 6-inch diameter, bears  $N49\frac{1}{2}^{\circ}W$ , 68.77 feet.

January 21, 1981  
R. Frost  
R. Templin

Edward McGinty  
County Surveyor

$V = 18\frac{3}{4}^{\circ}$   
P. -16


SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

## FOURTH RE-ESTABLISHMENT

GCDB 300100

Section corner common to Sections 32 and 33, Township 34 South, Range 1 West, and Sections 4 and 5, Township 35 South, Range 1 West, W.M.

Found the 3 ins. diam. brass cap set on the Third Re-establishment, dated 1981, 6 ins. deep. Cap marked;



From which bearing trees recorded in 1981 found and measured to center of tree at base:

- White Oak 15 ins. diam. with healed double blaze, marked on the First Re-establishment dated 1917, bears  $S34^{\circ}W$ , 12.55 feet. 1981 record 12.05 feet.
- White Oak 10 ins. diam. with healed double blaze, marked on the Second Re-establishment dated 1942, bears 1981 record  $S84\frac{3}{4}^{\circ}W$ , 97.58 feet
- Ponderosa Pine 22 ins. diam. with healed double blaze, marked in 1981, bears record  $S23^{\circ}E$ , 66.93 feet
- White Oak 8 ins. diam. with healed double blaze, marked in 1981, bears record  $N49\frac{1}{2}^{\circ}W$ , 68.77 feet

Set a new reference:

- $\frac{5}{8}$  x 24 ins. rebar with 2 ins. diam. aluminum cap marked;



flush with ground bears  $N59\frac{1}{2}^{\circ}E$ , 26.90 feet

Corner is located on flat area approx. 500 feet east of residence at 2760 Rogue River Dr.

March 22, 2016  
S. Beecher  
E. Madden

Scott D. Fein  
Jackson County Surveyor

P. 20-21  
 $V = 15^{\circ}$