

**FIRST RE-ESTABLISHMENT**

**GCDB 500200**

Section corner common to Sections 26, 27, 34 and 35, Township 34 South, Range 1 West, W.M.  
V = 19°

From the following evidence at the location described below, I set a 1x36-inch G.I. pipe, 30 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1978	
T34S,R1W	
27	26
-----	
34	35

Original bearing trees recorded by Ives and Hyde in 1854, found as follows:

- The base and stump hole of a down and rotted pine, 16-inch diameter, bears Record: S59°W, 45.54 feet.
- Pine stob, 10-inch diameter, scribed "R1W T34S S27" and "BT in exposed faces bears Record: N50°W, 38.94 feet to scribed face.
- The NE and SE BT are now gone.
- The stump hole of a down and rotted black oak (recorded line tree), 15-inch diameter, bears Record: North, 11.88 feet.

I mound stones around corner, mark new trees CS BT and take measurements to center of trees at lower blaze:

- Laurel, 8-inch diameter, bears N18°E, 12.95 feet.
- Black Oak, 5-inch diameter, bears S18°E, 20.54 feet.
- Laurel, 7-inch diameter, bears S33°W, 17.54 feet.
- Laurel, 6-inch diameter, bears N70¾°W, 26.50 feet.

Corner lies on North slope, about 230 feet North of ridge top and about 132 feet South of stream C. WSW.

January 4, 1978  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor