

FIRST RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13 and 14, Township 34 South, Range 1 West, W.M.

Set a 1" x 36" galvanized iron pipe 29" in the ground with a 2½" bronze cap stamped:

T34S R1W
¼ 14 | 13 Cor.
C.S.
1970

For corner from which:

- The original bearing tree, a 14" (now Black Oak snag with scribe marks visible) bears S22°W, 62.4 feet to the center of the tree. Marked new trees as follows:
- A 9" Cedar, scribed "CS-BT" bears S67°E, 18.9 feet to the face of the lower blaze;
- A 4" White Oak, scribed "CS-BT" bears N39°W, 28.3 feet to the face of the lower blaze.

December 17, 1970
O. Blankenship
J. Gartman

Approved By:
Mark E. Boyden
Jackson County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13 and 14, Township 34 South, Range 1 West, W.M.

Found at the corner, projecting 7 ins., leaning south, 1-inch diameter galvanized iron pipe with 2½-inch diameter brass cap marked:

T34S R1W
¼ 14 | 13 Cor.
C.S.
1970

As recorded on First Re-establishment page 22 in 1970.

- Straighten found pipe and measure extant bearing trees:
- Original bearing tree recorded by Ives and Hyde in 1854, now a Black Oak stump, 14-inch diameter with remains of tree alongside, bears Record: S22°W, 62.04 feet to estimated face.

First re-establishment bearing trees found:

- Cedar, 11-inch diameter containing scribed "S" & "BT" in partly exposed faces, bears S67°37'E, 18.92 feet to scribed lower face. Record: S67°E, 18.9 feet. Re-measure 19.3 feet to center of tree at lower blaze.
- White Oak, 5-inch diameter with healed blazes, bears N39°12'W, 28.4 feet to center of tree at lower blaze. Record: N39°W, 28.3 feet.

Corner lies near Southeast corner of field and about 20 feet East of small draw c. Southerly.

June 22, 1981

R. Frost

R. Templin

Witness: C. McLoughlin

Edward McGinty

County Surveyor

V = 20°

P.-96