

FIRST RE-ESTABLISHMENT

GCDB 200140

Quarter Section corner to Sections 31 & 32, Township 34 South, Range 2 East.

Found the original Southwest bearing tree, a black oak with BT scribe legible. Also found a stump hole which agrees with the southeast bearing tree.

Set a 1"x 28" galvanized iron pipe 26" in the ground for corner from which an 8" fir scribed CS-BT bears north $87\frac{1}{2}^{\circ}$ W 7.9 feet. Scribe a 16" fir CS-BT which bears South 27° E 14.7 feet.

April 9, 1954
C. Z. Boyden
L. D. Pinkham
M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 200140

Quarter corner common to Sections 31 and 32, Township 34 South, Range 2 East, W.M.

At the corner found projecting 3 ins., the 2½-inch diameter galvanized iron pipe, with the standard 3-inch diameter BLM brass cap marked:

T34S R2E
¼
S31 | S32
1968

Bearing trees marked on First Re-establishment, in 1954 found:

- Sawed Douglas Fir stump 24-inch diameter, with lower healed blaze, bears S27°E, 14.50 feet to face. Center is 15.00 feet. BLM Record: 15.18 feet.
- Douglas Fir, 9-inch diameter with healed blazes bears N84½°W, 8.0 feet to center of lower blaze. BLM Record: N87½°W, 7.92 feet.

Marked new trees "CS" "BT" and take measurements to the center of tree at lower blaze:

- Douglas Fir, 7-inch diameter, bears S31°W, 20.60 feet.
- Incense cedar, 7-inch diameter, bears S66½°E, 7.85 feet.

Set aluminum post 5½ feet long 18 ins. in the ground with sign attached which bears N50½°E, 6.25 feet.

Corner lies on level ground in recently logged unit and approximately 200 feet East of Cobleigh Road.

December 4, 1989
T. Newcomb, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

V = 20½°
P.-251

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 200140

Quarter corner common to Sections 31 and 32, Township 34 South, Range 2 East, W.M.

Found at the corner position, protruding 3 ins. from a mound of stones, the 2½-inch diameter galvanized iron pipe with a 3½-inch diameter brass cap set by the BLM in 1968, marked:

T34S R2E
 ¼
S31 | S32
 1968

Bearing trees recorded on Second Re-establishment in 1989, found and Re-measured to center of tree at lower blaze:

- Douglas Fir sawed stump, 24-inch diameter bears S27°E, 15.0 feet to center. BLM Record: 15.18 feet.
- Douglas Fir snag, now 10-inch diameter and high-stumped with healed blazes, bears N84½°W, 8.0 feet BLM Record: N 87½° W, 7.92 feet.
- Douglas Fir snag, now 8-inch diameter with healed blazes bears Record: S31°W, 20.60 feet.
- Incense cedar, now 9-inch diameter with healed blazes bears Record: S66½°E, 7.85 feet.
- Aluminum post with sign bears Record: S50½°E, 6.25 feet.

Mark new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Incense cedar 8-inch diameter bears N43¼°W, 20.6 feet.
- Douglas Fir 8-inch diameter bears S 3¼ W, 30.5 feet.
- Black Oak 6-inch diameter bears S 88½° E, 17.15 feet.

Corner lies approximately 200 feet easterly of Cobleigh Road.

October 23, 2003
H. Durkee

Roger R. Roberts
Jackson County Surveyor

P. - 153
V. - 20°