

## FIRST RE-ESTABLISHMENT

GCDB 600240

Quarter corner common to Sections 25 and 26, Township 34 South, Range 2 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1968, marked:

T34S R2E  
¼  
S26 | S25  
1968

Original bearing trees recorded by Eugene Henry of the GLO in 1908, found and measured to center at base:

- Cedar snag 34 ins. diam. with healed blazes, brs. N58½°E, 46.2 ft. record; N60¼°E.
- Cedar now 33 ins. diam. with healed blazes, brs. record; S73¼°W, 23.1 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- B. Oak 9 ins. diam. brs. N56°W, 20.0 ft.
- B. Oak 22 ins. diam. brs. N63°E, 27.2 ft.
- No trees practical in southeast quadrant.

Corner lies approx. 350 ft. north of gravel road.

October 17, 2011

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 61

V. – 15°40'