

**FIRST RE-ESTABLISHMENT
CLOSING CORNER TO SECTIONS 24 AND 25 ONLY
GCDB 700300**

Closing corner common to Section 24 and 25, Township 34 South, Range 2 East, W.M. $V = 19\frac{1}{2}^\circ$

From the following evidence, at the location described below, I set a 1x36-inch G.I. pipe, 34 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1977
T34S R2E
24
—
25

Original bearing trees recorded by E. B. Henry in 1908 found as follows:

- Laurel, 32-inch diameter, with axed into face, bears Record $S36^\circ W$, 43.56 feet on slope, to center. Re-measured: 41.69 feet to center of tree.
- Sawed Douglas fir stump, 36-inch diameter, scribed "T3R2ES24B" in partly exposed face, bears record $N36\frac{3}{4}^\circ W$, 9.24 feet to center.
- Found disturbed about 5 feet South of corner the original 15x11x9 inches stone, marked with 2 and 4 grooves on opposite and "CC" on adjacent side.
- The 1-inch diameter iron pipe noted on 1970, BLM dependent resurvey could not be found.

I mound stones around corner, mark the following trees CS BT and take measurements to center of trees at lower blaze;

- White fir, 8-inch diameter, bears $S80\frac{1}{2}^\circ W$, 38.19 feet.
- White fir, 11-inch diameter, bears $N66\frac{3}{4}^\circ W$, 39.55 feet to center.

November 1, 1977
B. Malotte
R. Frost
A. Rambo, Medco Corp.

Approved by: Edward McGinty
County Surveyor