

FIRST RE-ESTABLISHMENT

GCDB 100300

Section corner on the range line, Sections 24 and 25, Township 35 South, Range 3 West and Sections 19 and 30, Township 35 South, Range 2 West.

Found the 4" x 4" x 6" sandstone for corner. Also the remains of the original BTs to the Southeast and Northwest.

Replace sandstone corner monument with a 2" x 36" galvanized iron pipe set 8" below the surface of the County Road for corner from which a 12" Black Oak scribed C.S.-BT bears N85°E 29.4 feet.

The center of a 36" Black Oak (not scribed) bears S33°W 109.8 feet.

The center of a 36" Black Oak (not scribed) bears N85°W 67.0 feet. Set a 1¼" x 16" iron pin which bears S45°E 27.1 feet.

May 16, 1949
C. Z. Boyden
L. D. Pinkham
D. C. Inglis

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 100300

Section corner common to Sections 19 and 30, Township 35 South, Range 2 West and Sections 24 and 25, Township 35 South, Range 3 West, W.M.

At the corner, found 8 ins. deep, the 2 ins. diam. iron pipe set on first re-establishment, page 18, in 1949. Directly over said pipe, set a 2½ ins. diam. brass cap, in cement, flush with the surface of road, marked:

T35S	
R3W	R2W
24	19
25	30
C.S.	
1982	

References recorded in 1949 found as follows:

- Center punched, 1¼ ins. diam. iron pin, found 4 ins. deep, brs. Record: S45°E, 27.10 feet.
- Center of oak stump, 39 ins. diam., brs. Record: S33°W, 109.8 feet.
- Black Oak, 45 ins. diam. (not scribed) brs. Record: N85°W, 67.0 feet to center of tree.

Set new references; 5/8 x 30 ins. rebars, flush with the ground, with yellow plastic cap marked: JACKSON C.S. br;

- S89°48'E, 51.52 feet, located about 5 feet east of power pole no. B9755.
- S35°33'W, 55.85 feet, located 2 feet East of 8 ins. diam. Cedar.

Mark a new tree "CS" "BT":

- Black Oak, forked, 13 ins. diam., brs. N34°W, 48.85 feet to center of tree at lower blaze.

Corner lies near the intersection of Ramsey Rd. and Pelton Lane.

January 25, 1982

R. Frost

R. Templin

Edward McGinty

County Surveyor

V = 19°

P. -12

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT
GCDB 100300

Brass cap has been removed. Set new cap dated 1986, otherwise marked identical as 1982 brass cap.

April 15, 1986
R. Frost
T. Newcomb

P. -80

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 100300

Section corner common to Sections 19 and 30, Township 35 South, Range 2 West and Sections 24 and 25, Township 35 South, Range 3 West, W.M.

At the corner, found 4 ins. deep, the brass cap monument set on third re-establishment in 1986. Directly over said brass cap set a new brass cap marked:

R3W	T35S	R2W
24		19
25		30
C.S.		
1994		

References reported on second re-establishment in 1982 found:

- Center punched iron pin, found 6 ins. dep brs. record (basis of bearings); S45°00'E, 27.14 feet.
- Oak stump, now 32 ins. diam., brs. Record: S33°00'W, 109.8 feet to center.
- Black Oak, now 48 ins. diam., brs. Record: N85°00'W, 67.00 feet to center of tree at base.
- Rebar, 5/8 ins. diam., found 5 feet easterly of P.P. B-9755, brs. S89°11'28"E, 51.49 feet. Record (1982); S 89°48'E, 51.52 feet.
- Rebar, 5/8 ins. diam., found 2 feet easterly of 9 ins. diam. cedar, brs. S35°27'50"W, 55.84 feet. Record (1982); S35°33'W, 55.85 feet.
- Black Oak, 14 ins. diam. with healed blazes brs. Record: N34°00'W, 48.85 feet to center of tree at lower blaze.

Take a new reference; "chiseled cross atop outlet (east) end of a 12 ins. diam. concrete culvert, brs. N28°01'30"E, 27.04 feet.

Corner lies 14 feet north of the (visual) P.I. of Pelton Lane and Ramsey Road.

September 27, 1994
R. Frost, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

P. -130

NOTE: Section corner is also Jackson County G.P.S. Station No. 195.