

FIRST RE-ESTABLISHMENT

GCDB 240200

Quarter corner 29 and 32, Township 35 South, Range 2 West, W.M.

Found stumps of both original witness trees and set stake for corner

From which:

- An 8" White oak bears N. 35° W., 32.6 feet;
- An 8" White oak bears S. 8½° W., 112.0 feet;

February 17, 1915
A. T. Brown, County Surveyor
H. Ling, H.L. Speck, Chainmen

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SPECIAL CORNER

SECOND RE-ESTABLISHMENT

GCDB 240200

Quarter corner common to Sections 29 and 32, Township 35 South, Range 2 West, W.M.

Found 3 ins. deep in the middle of Old Sams Valley Rd., the center punched rail-road spike set on Survey No. 1911 (Sam's Valley Park Subdivision, dated 1961) by proportionate method. To perpetuate this location, directly over said railroad spike, set a 2½ ins. diam. brass cap in concrete, marked:

T35S R2W
29
¼S □
32
C.S.
1987

References reported on the above noted survey found:

- A 2 ins. diam. galvanized iron pipe found 6 ins. deep, 18 ins. North of the (wood) post corner of North and East-West fence lines, being the initial point of Sam's Valley Subdivision, brs. N0°11'W, 29.96 feet Record: 30.0 feet
- A stump depression is found at the record location of the Southeast bearing tree.
- No evidence found of bearing trees recorded on First re-establishment, dated 1915.

Take new references:

- A found smooth iron pin, ½ in. diam., projecting 4 ins. on East-West fence line, brs. N4°49'E, 28.52 feet.
- Black Oak, 9 ins. diam., scribed "CS" "BT", brs. S63°39'E, 66.67 feet to center of tree at lower blaze.
- A smooth iron pin, ½ in. diam. found flush with wire coiled near top, brs. S1°05'W, 30.36 feet.
- Transmission line access road, brs. S36°34'W, 22.86 feet.

Corner lies 170 feet East of middle of County bridge No. 649 crossing rock creek and about 50 feet East of center wire of (3wire) overhead transmission line.

March 23, 1987
R. Frost
E. McGinty

Edward McGinty
County Surveyor

P. -84