

FIRST RENEWAL

GCDB 240400

Quarter corner common to Sections 17 and 20 T35S R2W.

Set a 1" x 36" galvanized iron pipe with bronze cap stamped:

T35SR2W
¼ Cor. 17 C.S.
—
20
1962

30" in the ground for corner,

From which:

- The original witness tree (now a 26" Black Oak with scribe marks plain) bears South 32° West, 35.6 feet;
- The original witness tree (a Laurel, down and badly decayed, lying below the remaining ½ ring of a Laurel stool), the center of said stool bears North 46° East, 29 feet;

I mark new witness trees as follows:

- A 7" Fir, scribed "CS-BT" bears North 51° West, 11.9 feet to the face of the upper blaze;
- A 14" Fir, scribed "CS-BT" bears South 80° East, 3.8 feet to the face of the upper blaze;
- A ¾" iron pipe with pin inside bears North 14° East, 4.73 feet.

February 26, 1962
L. D. Pinkham
C. L. Birk

Approved By:
Mark E. Boyden
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 240400

Found, projecting 7 ins. the 1 ins. diam. G.I. pipe with brass cap marked:

T35S R2W
¼ 17
— C.S.
COR 20
1962

Set on first re-establishment, page 23, in 1962.

An original bearing tree recorded by Ives and Hyde in 1854, a black oak, now 26 ins. diam., scribed "BT" in exposed lower face, brs. S32°W, 35.50 feet to scribed face. Record: S32°W, 35.64 feet.

Reference trees marked on first re-establishment found as follows:

- Fir snag, 16 ins. diam., with healed blazes, brs. record S80°E, 3.80 feet to estimated upper face.
- Fir snag, 7 ins. diam. with healed blazes, brs. Record: N51°W, 11.9 feet to scribed upper face.
- A found iron pin in ¾ ins. diam. iron pipe, projecting 6 ins. brs. as recorded on first re-establishment, N14°E, 4.73 feet.

I mk. new trees CS BT, and take measurements to center of trees at lower blaze:

- Cedar, 10 ins. diam., brs. S52°W, 46.36 feet
- White Oak, 12 ins. diam., brs. N21°W, 41.75 feet.

Corner lies near (down) East-West fence line, about 400 feet. East of location marker on 18 ins. diam. Fir alongside road, Course N10°W.

June 3, 1979
J. Swanson
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 240400

Quarter corner common to Sections 17 and 20, Township 35 South, Range 2 West, W.M.

Found projecting 10 ins. the 1 ins. diam. galvanized iron pipe, with a 2½ ins. diam. brass cap set on first re-establishment, dated 1962 marked:

T35SR2
W
17
¼ ————— C.S.
20
Cor. 1962

Bearing trees marked on second re-establishment, dated 1979 found with partially healed blazes and measured to the center of tree at lower blaze:

- Burned oak snag 12 ins. diam., brs. Record: N21°W, 41.75 feet.
- Burned cedar snag 12 ins. diam., brs. S52°W, 46.70 feet. Record: 46.36 feet.
- ¾ ins. diam. iron pipe with iron pin inside brs. N11½°E, 4.70 feet. Record: N14°E, 4.73 feet.

New references set; 5/8 x 24 ins. diam. rebar with aluminum caps marked "Jackson County CS" and directly behind references set a small 36 ins. long metal fence post with location tag attached:

- Projects 2 ins., brs. S45°W, 20.80 feet.
- Projects 5 ins., brs. N45°W, 21.75 feet.
- Projects 3 ins., brs. N45°E, 16.05 feet.
- Projects 3 ins., brs. S45°E, 20.80 feet.

Corner lies on north slope, burned over by Hull Mtn. fire, August of 1994. Location tag on east side of road 400 feet west of corner.

October 5, 1994
T. Newcomb, Tech.
R. Frost, Tech.

Verlyn Thomas
County Surveyor

V = 17°
P.-153