

FIRST RE-ESTABLISHMENT

GCDB 400440

Quarter Corner to Sections 15 and 16, Township 35 South, Range 2 West, W.M.

Found original BT to northeast; from which evidence

- Set a 1" x 30" iron pipe 24" in the ground for corner,

From which:

- A 22" white oak scribed C.S.-BT bears S.21¼°E., 23.25 feet.
- Scribed a 6" white oak C.S.-BT which bears N.31°W., 38.1 feet.

November 28, 1944
C. Z. Boyden
B. L. Campbell
R. E. Welch

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400440

Quarter corner common to Section 15 and 16, Twp. 35 South, Range 2 West, W.M. $V = 20^\circ$

Found the 1 inch iron pipe exposed 6 ins. as set for first re-establishment by County Surveyor in 1944.

BTs found as follows:

- The original BT, now an 18 ins. white oak with opened blaze bears $N31\frac{3}{4}^\circ E$ 49.0 feet to center of tree.
- The S.E. BT marked in first re-establishment, now a 24 ins. white oak, bears $S20\frac{1}{4}^\circ E$ to lower blaze, 24.3 feet to center.
- The 9 ins. diam. stump of a white oak, apparently the N.W. BT marked in first re-establishment, bears $N31^\circ W$ 38.3 feet to center.

I marked a new B.T:

- A 4 ins. White Oak, scribed C.S. BT, bears $S58^\circ W$ 27.85 feet to center.

Corner lies 1 feet east of a north-south fence line and 5.5 feet south of a deteriorated easterly fence line.

August 17, 1976
Ed Graham
R. Roberts

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 400440

Quarter corner common to Sections 15 and 16, Township 35 South, Range 2 West, W.M.

Found projecting 3 ins., the 1 ins. diam. iron pipe as recorded on first re-establishment, in 1944. In the top of said pipe set a 2½ ins. diam. brass cap marked:

T35S R2W
¼S
16 | 15
CS
1989

The single remaining bearing tree recorded by Ives and Hyde in 1854 found:

- A hollow White Oak 20 ins. diam., brs. (1976 record); N31¾°E, 49.0 feet to center of tree at base.

Bearing tree marked on first re-establishment found:

- White Oak 25 ins. diam., with healed blazes brs. S20¼°E, 24.10 feet to center of tree at lower blaze. Record: S21¼°E, 23.25 feet.

Bearing tree marked on second re-establishment, in 1976 found:

- White Oak, 4 ins. diam., with healed blazes brs. S59¼°W, 27.80 feet to center of tree at lower blaze. Record: S58°W, 27.85 feet.

Unrecorded bearing tree found:

- White Oak, 6 ins. diam. with healed blazes, brs. N76¼°W, 34.10 feet to center of tree at lower blaze.

Corner lies 1 foot South of fence corner with fence wire projecting south and west and 5 feet south of fence corner with fence wire projecting south and east.

August 31, 1989
T. Newcomb, Tech.
S. Beecher, Tech.

Verlyn Thomas
County Surveyor

V = 17¾°

SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT

FOURTH RE-ESTABLISHMENT

GCDB 400440

Quarter corner common to Sections 15 and 16, Township 35 South, Range 2 West, W.M.

Found at the corner position, projecting 3 ins., the 1 in. diam. galvanized iron pipe with 2½ ins. diam. brass cap recorded on Third Re-establishment in 1989 and marked:

T35S R2W
¼ S
16 • 15
CS
1989

Bearing trees recorded on said 3rd Re-establishment, found and measured to center of trees at lower blaze:

- Burnt White Oak snag 4 ins. diam. brs. record S59°15'W, 27.80 feet.
- Hollowed out White Oak 25 ins. diam. with healed blazes brs. S20°13'44"E, 24.10 feet.
Record S20¼°E.

New references taken, 5/8 x 24 ins. rebars projecting 4 ins. with 1½ ins. diam. aluminum caps marked:

JACKSON COUNTY

SURVEYOR

Bear:

- S59°15' W, 22.02 feet.
- N53°48'40" W, 19.08 feet.
- S41°56'40" E, 22.41 feet.

Corner lies northerly of dirt road and S36°E, 1.5 feet of northerly, 6 x 6 ins. wooden gate post.

August 28, 2003

H. Durkee
T. Newcomb

Roger R. Roberts
Jackson County Surveyor

P. - 133