

FIRST RE-ESTABLISHMENT

GCDB 440600

Quarter corner Section 3 and 10, Township 35 South, Range 2 West, W.M.

Found the black oak bearing tree in Section 10 intact and the decayed stump of the yellow pine in Section 3.

Set a sandstone 1 x 7 x 12 inches 10 inches in the ground according to the call in the field notes. Cut across for corner on the stone and marked $\frac{1}{4}$ on the North face.

- Set a new witness tree a 10 fir which bears N.44°E., 23.9 feet from the $\frac{1}{4}$ section corner.

A. T. Brown
Deputy County Surveyor
Bill Worrell and Frank _____, Chainmen.

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 440600

Quarter corner common to Sections 3 and 10, Township 35 South, Range 2 West, W.M.

Found the 1½" x 9" x 16" sandstone as set for corner on the first re-establishment by Deputy County Surveyor A. T. Brown.

Replaced said stone with a 1" x 36" galvanized iron pipe, 33" in the ground with a 2½" bronze cap stamped:

T35S R2W
3
¼ — Cor.
10
C.S.
1971

From which:

- The original bearing tree (now a 16" Black Oak with healed blazes) bears S35°E, 37.3 feet;
- A Pine stump hole bears N34½°W, 34.1 feet to the center.
- The first re-establishment bearing tree (now a 24" Fir with healed blazes) bears N43½°E, 24.1 feet to the center.

I mark a new tree as follows:

- A 12" pine, scribed "CS-BT" bears S46°W, 22.6 feet to the face of the lower blaze.

August 12, 1971
Gary D. Kaiser, Deputy County Surveyor
Lloyd Shreeve

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 440600

Quarter corner common to Sections 3 and 10 of Township 35 South, Range 2 West, W.M.

Found at corner position exposed 2 ins. the 1 in. diam. galvanized iron pipe with a 2½ ins. diam. brass cap set on SECOND Re-establishment in 1971 marked:

T35S R2W
3
¼ — COR
10
C.S.
1971

Single remaining original bearing tree recorded by Ives and Hyde of the GLO in 1854 found with a healed blaze and measured to center at base:

- Black Oak now 18 ins. diam. brs. Record: S35°E, 37.3 feet.

The single bearing tree recorded on First Re-establishment in 1914 found with healed double blazes and measured to center at lower blaze:

- Fir snag brs. Record: N43½°E, 24.1 feet.

Bearing tree recorded on said SECOND Re-establishment found with healed double blazes and measured to center at lower blaze:

- Pine, now 18 ins. diam., brs. S46°W, 23.2 feet. Record: 22.6 feet to face.

Marked new bearing trees "CS "BT" and measured to center at lower blaze:

- White Oak 9 ins. diam. brs. N60°W, 24.7 feet.
- White Oak 7 ins. diam. brs. N21¾°E, 4.8 feet.

Corner lies approximately 600 feet east of Meadows Road.

September 5, 2007

B. Beeman
H. Durkee

Roger R. Roberts
Jackson County Surveyor

P - 207
V - 14°50'