

FIRST RE-ESTABLISHMENT

GCDB 600440

Re-establishment Quarter section corner Sections 13 & 14, Township 35 South, Range 2 West.

Found sand stone with X on top, from which the stump hole of a black oak tree N 5° W checks the official record. County Surveyor A.T. Brown set the above mentioned sand stone corner in 1910 from the original BT to NW which stump and scribe was in place.

From the said sand stone with X for corner

- An 8" twin white oak scribed CS-BT bears S.43°30' W. 62.0 feet.
- Scribe a 36" white oak which bears N.25½°W 159.7 feet.

August 21, 1930

C. Z. Boyden

L. Pettegrew

Dave King

NOTE

New BT: Scribe a 20" white oak, which bears N. 59¼°E. 440.0 feet. November 1, 1944 (C.Z.B.)

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13 and 14, Township 35 South, Range 2 West, W.M.

Found sandstone with X on top and BTs as follows:

- Found Twin White Oak, now 12 ins. diam., bears $S43^{\circ}30'W$, 62.0 feet with healed faces, as per 1930 notes, placed tag.
- Found charred Oak stump, bears $N25^{\circ}W$, 160 feet, as per 1930 notes
- Found White Oak now 24 ins. diam., bears $N59^{\circ}15' E$. Distance not checked (Record = 440 feet.) with healed faces as per 1944 notes.

New RPs:

- Found $\frac{5}{8}$ ins. iron pin, bears $N89^{\circ}59'55''W$, 620.32 feet (R.S. #5224)
- A $\frac{5}{8}$ ins. x 32 ins. re-bar set 18 ins. in the ground in a mound of stone, bears $N30^{\circ}05'E$, 90.0 feet.
- A $\frac{5}{8}$ ins. x 32 ins. re-bar set 24 ins. in the ground, bears $N60^{\circ}49'W$, 75.0 feet.

April 26, 1973

E. Graham

B. Black

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Section 13 and 14, Township 35 South, Range 2 West, W.M.

Found sandstone with "X" on top protruding 1 ins. above ground, said stone being set by County Surveyor A.T. Brown in 1910 from original evidence. Remove stone (21 ins. x 7 ins. x 6 ins.) and set a 1 ins. x 36 ins. galvanized iron pipe with 2½ ins. diam. brass cap marked:

T35S R2W
¼S
14 | 13
C.S.
1989

Set in cement in top 1 ins. above ground.

First re-establishment, pg. 5, dated 1930 & 1944, references found:

- White Oak 32 ins. diam., with healed blazes brs. N59°13'E, distance not measured. Record: N59¼°E.
- White Oak 18 ins. diam., the Northeast branch of a twin, with healed blazes brs. S43°09'W, 62.0 feet. Record: S43°30'W, hits center of main trunk.

Second re-establishment, pg. 36, dated 1973, reference found:

- 5/8 ins. rebar protruding 18 ins. above ground and bent brs. Record: N30°05'E, 90.0 feet to where it enters ground.

Set a 5/8 in. x 24 ins. rebar with yellow plastic cap marked JACKSON CS, flush with ground 5.5 feet South of an anchor post to North, East and West bearing fence lies brs. S81°35'E, 12.43 feet.

Corner lies S69°28'W, 12.8 feet of an anchor post (8 x 10 x 78) ins. of North, East and West bearing fence lines and 4.3 feet South of an East-West fence.

August 30, 1989
S. Beecher
T. Newcomb

Verlyn Thomas
County Surveyor

P.-182