

FIRST REESTABLISHMENT

GCDB 300640

Re-establishment Quarter corner to Sections 4 and 5, Township 36 South, Range 1 East, W.M.

Found the 6" x 6" x ? stone with cross on top and the 20" White Oak witness tree which bears South $\frac{1}{2}^{\circ}$ East, 373.2 feet as established by County Surveyor Elksnat in 1909.

From said stone monument:

- Scribed a 12" twin White Oak "CS-BT" (on one blaze) which bears North $\frac{1}{2}^{\circ}$ W, 365.0 feet.
- The Northwest corner of a one-story wood frame residence bears S32 $\frac{1}{2}^{\circ}$ E, 179.4 feet.

April 9, 1957
C. Z. Boyden
K. D. Weaver

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 300640

Quarter corner common to Section 4 and 5, Twp. 36 South, Range 1 East, W.M. $V = 21^\circ$

Found 6x6x? stone, marked with "X" on top, 10 ins. deep on east-west fence line.

BTs noted by C. Z. Boyden on first re-establishment, found as follows:

- A White Oak, 35 ins. diam. (G. Elksnat) bears $S0\frac{1}{2}^\circ E$, 373.9 feet to center. Record, $S\frac{1}{2}^\circ E$, 373.2 feet.
- A White Oak, 16 ins. diam., with healed blaze, bears $N\frac{1}{2}^\circ W$, 366.1 feet to center. Record, $N\frac{1}{2}^\circ W$, 365.0 feet.

I set $\frac{5}{8} \times 21$ ins. re-steel rods, flush with the ground as follows:

- Under East-West fence, bears $S85^\circ 30' E$, 15.7 feet.
- 1 feet Northwest of corner of the concrete foundation of a wood frame shed, bears $S11^\circ 45' W$, 5.70 feet.

Corner lies about 275 feet North of center of road.

April 28, 1975
R. Frost
G. Cunningham

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 300640

Quarter corner common to Sections 4 and 5, Township 36 South, Range 1 East, W.M.

Found stone 8 ins. deep and "x" on top set by Elksnat in 1909. Remove stone (6 x 6 x 15 ins.) and replace with a 1 x 36 ins. galvanized iron pipe with 2½ ins. diam. brass cap marked:

T36S R1E
¼S
5 | 4
CS
1989

Cemented in top protruding 1 in. above ground From which:

References from the Second Re-establishment dated 1975 found:

- ½-in. diam. rebar 1 in. below ground surface on an East-West fence line brs. S85½°E, 15.65 feet. Record distance; 15.7 feet.
- ½-in. diam. rebar flush with the ground and 1 feet Northwest of the Northwest corner of concrete foundation of shed with newer addition attached to West side brs. record S11¾°W, 5.70 feet.
- Take new references:
- A found bolt with 1 ⅛ in. square head protruding 5 ins. above ground on East-West fence line brs. S85°E, 4.42 feet.
- Cherry tree 8 ins. diam. unmarked brs. S85°W, 39.0 feet.

Corner lies on East-West fence line behind residence 5313 Brownsboro.

Highway and approximately 80 feet East of fence corner of East-West and north bearing fence lines.

October 6, 1989
S. Beecher, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 18¾°
P. -221