

FIRST RE-ESTABLISHMENT

GCDB 440300

Quarter corner common to Sections 22-27, Township 36 South, Range 1 East.

Found the two original witness trees. The black oak in Section 22 dead and decayed at the heart. Set a ½" gas pipe for corner and set one new witness tree, a 30" yellow pine which bears N.64°W., 71.3 feet from the ¼ corner.

April 10, 1914
A.T. Brown, Deputy County Surveyor
H. Ling, Chainman
Philo Murphy, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 440300

Quarter corner common to Sections 22 and 27, Township 36 South, Range 1 East, W.M. $V = 19^\circ$

Found at base of 6 ins. diam., Black Oak, a 6 x 6 ins. concrete pedestal, projecting 4 ins. with imbedded $3\frac{1}{2}$ ins. brass cap marked:

U.S. ENGINEER DEPARTMENT
Portland District

Boundary Monument

At the record location of the original S.E. and N.E. BTs, as noted by Ives and Hyde in 1854, are a Laurel cluster and two small (6 and 8 ins. diam.) Black Oaks respectively.

- A Yellow Pine, marked by A.T. Brown in 1914, on First Re-establishment, page 2, now 36 ins. diam., bears $N64^\circ W$, 71.8 feet to center of tree. Record, $N64^\circ W$, 71.3 feet.

Monument set by Brown ($\frac{1}{2}$ ins. diam. gas pipe) was not found

I stamp the following information of afore-mentioned brass cap:

T36S R1E
22
 $\frac{1}{4}S$ —
27

And marked new trees C.S. BT:

- A Black Oak, 7 ins. diam., bears $N44\frac{1}{2}^\circ E$, 32.0 feet to center of tree at lower blaze.
- A White Oak, 7 ins. diam., bears $S81^\circ W$, 22.6 feet to center of tree at lower blaze.
- Southerly and Westerly bearing fence lines intersect approximately $S20^\circ W$, 29 feet from brass cap.

February 25, 1974
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor