

## FIRST RE-ESTABLISHMENT

GCDB 500340

Quarter corner common to Sections 22 and 23, Township 36 South, Range 1 East, W.M.

From the following original evidence, at the location described below, set a 1x36 ins. galvanized iron pipe, 30 ins. in the ground, with a 2½ ins. diam. brass cap marked:

T36S R1E  
¼S  
22 | 23  
C.S.  
1989

Original bearing trees recorded by Ives and Hyde in 1854 found as follows:

- A decayed oak (negative) axe face, containing reverse impression of scribed "BT" is found at record location, i.e. S66°W, 58.08 feet, of Southwest bearing tree.
- Remains of broken-off stump shell, about 12 ins. diam. brs. Record: N88°E., 46.20 feet to estimated position of original face.

Mark new trees, "CS" "BT", and take measurements to center of trees at lower blaze:

- Black Oak, 12 ins. diam., brs. S55¼°W, 19.29 feet.
- Black Oak, 11 ins. diam., brs. S85°E, 4.97 feet.

Corner lies on 25° westerly slope, and West, 0.5 feet of north-south fence line.

April 26, 1989  
H. Durkee, Tech.  
T. Newcomb, Tech.

Verlyn Thomas  
County Surveyor

V = 18°  
P.-130