

FIRST RE-ESTABLISHMENT

GCDB 600300

Section corner common to Sections 23, 24, 25 and 26, Township 36 South, Range 1 East, W.M.

Found projecting 18 ins., the 2 ins. diam. iron pipe reported set on Survey No. 2220. Replace said pipe with a 1 x 36 ins. galvanized iron pipe set 30 ins. in the ground. In the top of said pipe, set in concrete, a 2½ ins. diam. brass cap marked:

T36S R1E	
23	24

26	25
C.S.	
1988	

Note: Pipe is leaning but cap is good.

Original bearing tree marked by Ives and Hyde in 1854 found:

- Stump hole, with scribed "S" found in Oak shell lying alongside bears Record: N71°E, 80.6 feet to estimated position of face. Record distance; 83.16 feet.
- Stump hole, with scattered Oak remains alongside, brs. S70¾°W, 53.2 feet to estimated center of hole. Record; S70°W, 50.82 feet.

Bearing trees marked on said Survey No. 2220 found with double healed blazes and measured to center of tree at lower blaze:

- Black Oak, now 13 ins. diam., brs. N74½°E, 36.77 feet. Record; N74°20'E, 37.30 feet.
- White Oak, now 9 ins. diam., brs. S42¼°E, 20.1 feet. Record; S44°30'E, 20.1 feet.
- White Oak, now 9 ins. diam., brs. S85½°W, 24.2 feet. Record; S83°30'W, 24.60 feet.
- White Oak, now 7 ins. diam. with partial scribe marks visible in both faces, brs. N34½°W, 10.90 feet. Record; N30°30'W, 10.20 feet.

Corner lies in Oak openings, 15 feet West of a fence bearing N34°E-S34°W, on a 30% N70°E slope.

March 15, 1988
D. Edwards, Tech.
T. Newcomb, Tech.

Edward McGinty
County Surveyor

V = 18½°

P. - 94