

FIRST RE-ESTABLISHMENT

GCDB 100640

Quarter corner common to Section 1, Township 36 South, Range 2 East and Section 6, Township 36 South, Range 3 East, W.M.

Found at the corner position, cemented in and flush with a 4 ins. high rock outcrop, the 3½ ins. diam. brass cap set by the BLM in 1963, marked:

T36S
R2E • R3E
¼
S1 | S6
1963

Bearing trees recorded by the BLM in 1963, found with healed single blazes and measured to center of trees at base:

- White Fir now 21 ins. diam. bears N50°W, 18.5 feet. Record: 15.5 feet.
- Rotted fir remains br. Record: S60°E, 9.9 feet to center of stump hole.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- White Fir 14 ins. diam. bears S59°W, 22.5 feet.
- Due to clear-cut, no trees available to the east.

Corner lies approximately 200 feet north of gravel road.

December 12, 2006

H. Durkee

B. Beeman

Roger R. Roberts

Jackson County Surveyor

P. - 218

V. - 14°45'

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT
GCDB 100640**

Standard corner common to Section 1, Township 36 South, Range 2 East and Section 6, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1963, marked:

—
S1 | S6
R2E R3E
T36S
S.C.
1963

Bearing tree recorded by the BLM in 1963, a down rotted fir stump with scribe marks "T36S R3E SC BT" on partially healed face brs. record; S42°W, 25.7 ft. to center of stump hole.

Bearing trees recorded on 1st Re-establishment in 2006, found with partially healed double blazes revealing scribe marks "CS" "BT" and measured to center at lower blaze:

- Cedar, now 10 ins. diam. brs. record; S3½°E, 58.8 ft.
- W. fir now 6 ins. diam. and broken off approx. 10 ft. high by logging brs. record; S64°W, 22.0 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- W. fir 8 ins. diam. brs. S88¼°W, 37.8 ft.

Corner lies approx. 200 ft. easterly of bend in gravel road. C. – northerly and westerly.

October 16, 2008

H. Durkee
B. Beeman

Roger R. Roberts
Jackson County Surveyor

P. – 202
V. – 14°20'