

## FIRST RE-ESTABLISHMENT

GCDB 300300

Section corner common to Sections 20, 21, 28, and 29 of Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 10 ins., in a mound of stones, with the original stone alongside, the 2 ins. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the GLO in 1956 and marked:

T36SR3E  
S20 | S21  
—+—  
S29 | S28  
1956

Aluminum post with sign 1 ft. north and a Carsonite post with sign 6 ft. east.

Original bearing trees recorded by Rufus Moore of the GLO in 1883 found and measured to center;

- Fir rotted shell remains brs. record S27°W, 25.1 ft.
- Chinquapin now a sprouted clump brs. record N23°W, 24.4 ft.

Bearing trees recorded by the GLO in 1956 found with healed single blazes and measured to center at base;

- Fir snag brs. record S37°E, 23.8 ft.
- D. fir now 29 ins. diam. brs. record S37½°W, 28.4 ft.
- D. fir now 17 ins. diam. brs. record N64°W, 16.5 ft.

Bearing tree recorded by the BLM in 1981 found with a healed double blaze and measured to center at base;

- D. fir now 19 ins. diam. brs. record N71¾°W, 11.4 ft.

Marked a new bearing tree 'CS''BT' and measured to center at lower blaze;

- W. fir 13 ins. diam. brs. S4°E, 80.1 ft.

Corner lies approx. 400 ft. west of dirt road and approx 10 ft. west of north-south course fence line.

January 5, 2010

B. Beeman

Kerry K. Bradshaw  
Jackson County Surveyor

P. -3

V. - 13°45'