

FIRST RE-ESTABLISHMENT

GCDB 400100

Section corner common to sections 33, 34, Township 36 South Range 3 East; and section 3 and 4 Township 37 South Range 3 East, W.M.

Corner was disturbed and by private land owner and subsequently reported to this office by D. Weller of BLM Cadastral Survey. Utilizing corner accessories from survey number 8783 for Rogue River National Forest by Harold Center, PLS 1071 said section corner was reestablished. At position set a 1 ins. diam. by 30 ins. long flanged GIP with a 2 ½ ins. diam. brass cap MKD:

JACKSON COUNTY SURVEYOR

T36S R3E

33 | 34

4 | 3

T37S

2009

UNLAWFUL TO DISTURB

Found references from survey number 8783:

- 3 ins. diam. brass cap in 6 inch concrete square MKD:

DEPARTMENT OF COMMERCE

BUREAU OF PUBLIC ROADS



B.M. ELEV.

1) Brs: N51°41'35"W, 452.76 ft. (record)

2) Brs: N64°35'33"W, 375.09 ft. (record)

- 29 ins. diam. cedar with single healed blaze, Brs: N43°16'E, 65.00 ft. (record: 19 ins. diam., N43°12'E, 65.00 ft.).
- 26 ins. diam. cedar with single healed blaze, Brs: S55°41'E, 112.55 ft. (record: 21 ins. diam. S 23° 32'E, 112.90 ft.)

References taken this Reestablishment:

- 8 ins. diam. cedar with upper blaze "CS", lower blaze "BT", Brs: N41°50'W, 67.61 ft.
- 5/8-ins. by 24 ins. long rebar with 1½-ins. diam. aluminum cap MKD: Jackson County Surveyor Brs: N4°45'27"E, 54.49 ft. Lies on W. Side of N/S gravel driveway of 24800 Hwy. 140.

June 19, 2009

S. Fein

S. Beecher

Kerry K. Bradshaw

County Surveyor

Series II, Book I

P. 35-38