

FIRST RE-ESTABLISHMENT

GCDB 400600

Section corner common to Sections 3, 4, 9 and 10, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 9 ins. with the original stone alongside, the 2½ ins. diam. galvanized iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962, marked:

T36S R3E	
S4	S3

S9	S10
1962	

Original bearing trees recorded by R. Moore of the GLO in 1883, found and measured to center at base:

- Rotted fir snag bears Record: S17°E, 22.4 feet.
- Rotted fir stump bears S84°W, 23.1 feet. Record: S81°W.

Bearing trees recorded by the BLM in 1962, found and measured to center at base:

- Fir, dead and down, bears Record: N37°E, 13.2 feet.
- Yew, now 12 ins. diam. with partially healed single blaze revealing illegible scribe marks bears Record: S63°E, 32.3 feet.
- Fir, dead and down, bears Record: S28°W, 41.6 feet to center of stump hole.

Bearing trees of unknown origin found and measured to center at base:

- Douglas Fir 10 ins. diam. with a pitched-over single blaze and a "Lone Rock Timber" tag, bears S12¼°W, 11.1 feet.
- Cedar 11 ins. diam. with healed double blazes bears N24°W, 19.5 feet.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Cedar 9 ins. diam. bears N75°E, 9.0 feet.

Corner lies approximately 350 feet northeasterly from logging road at top of spur ridge.

April 24, 2007

H. Durkee
B. Beeman

Roger R. Roberts
Jackson County Surveyor

P. - 103
V. - 15°45'