

## FIRST RE-ESTABLISHMENT

GCDB 440500

Quarter corner common to Sections 10 and 15, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 16 ins. in a large mound of stones, the 2½ ins. diam. galvanized iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962, marked:

T36S R3E  
S10  
¼S —  
S15  
1962

Bearing trees recorded by the BLM in 1962, found with healed single blazes and measured to center of trees at base:

- Douglas Fir, now 16 ins. diam. bears Record: N2°W, 21.1 feet.
- High-stumped and tipped-over fir bears Record: S7°E, 13.9 feet to center of stump hole.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- White Fir 11 ins. diam. bears N70½°E, 25.3 feet.
- Douglas Fir 10 ins. diam. bears S16°W, 27.4 feet.
- No trees of size within limits in southeast quadrant.

Corner lies approximately 300' east of graveled logging road.

December 12, 2006

H. Durkee  
B. Beeman

Roger R. Roberts  
Jackson County Surveyor

P. - 223  
V. - 15°10'