

FIRST RE-ESTABLISHMENT

GCDB 600500

Section corner common to Sections 11, 12, 13 and 14, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T36S R3E
S11 | S12
—+—
S14 | S13
1966

Original bearing trees recorded by R. Moore of the GLO in 1883, found with healed blazes and measured estimated face:

- Fir snag brs. record; N39°E, 31.0 ft.
- Fir snag brs. record; S20°W, 13.2 ft.
- Large Cedar, dead and down, brs. record; N21°W, 51.5 ft.

Bearing trees recorded by the BLM in 1966, found with healed single blazes and measured to center at base:

- W. Fir, now 12 ins. diam. brs. record; N29°E, 10.9 ft.
- W. Fir, now 13 ins. diam. brs. record; 69°E, 15.8 ft.
- W. Fir, dead and down, brs. record; S12°W, 32.3 ft.
- W. Fir, now 14 ins. diam. brs. N13°W, 13.2 ft. Record; N 12° W.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- W. Fir 10 ins. diam. brs. S62¼°W, 8.3 ft.

Corner lies approx. 400 ft. south of gravel logging road.

April 2, 2012

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 160

V. – 15°40'