

## FIRST RE-ESTABLISHMENT

GCDB 600600

Section corner common to Sections 1, 2, 11 and 12 of Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins., in a mound of stones, and a Carsonite post with sign 4 ft. south, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962 and marked:

T36SR3E  
S2 | S1  
—+—  
S11 | S12  
1962

Original bearing trees recorded by Rufus Moore of the GLO in 1883 found and measured to center at base;

- D. fir rotted sawed stump brs. record; N48°E, 23.1 ft.
- D. fir now 23 ins. diam. with a healed blaze brs. S48°E, 11.6 ft. record; S41°E, 10.6 ft. to face.
- Chinquapin stob brs. N12°W, 35.7 ft. record; 35.0 ft. to face.

Bearing trees recorded by the BLM in 1962 found with healed single blazes and measured to center at base;

- D. fir now 14 ins. diam. brs. record ; N33°E, 30.4 ft.
- W. fir high stump brs. S32°E, 44.2 ft. record ; S30°E
- W. fir snag brs. S32°W, 28.4 ft. record ; S34°W.
- W. fir now 19 ins. diam. brs. record ; N64°W, 13.2 ft.

Marked a new bearing tree 'CS''BT' and measured to center at lower blaze;

- W. fir 10 ins. diam. brs. S49¼°W, 19.8 ft.

Corner lies approx. 500 ft. west of old dirt road.

May 24, 2010

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -122

V. - 15°15'