

## FIRST RE-ESTABLISHMENT

GCDB 640300

Quarter Section corner between Sections 24 and 25, Township 36 South, Range 3 East, W.M.

Found the 16" x 10" x 8" basalt stone for corner marked  $\frac{1}{4}$  on face, no evidence of the two bearing trees. Using the stone for the location of the corner, set a 1" x 36" galvanized iron pipe with a 1½" expander on top filled with pot metal and stamped:

"T36S, R3E  
24  
 $\frac{1}{4}$ S — Cor. C.S.  
25

The top of the pipe was set 6" below the surface of the ground for corner and the said stone marked  $\frac{1}{4}$  directly above the pipe corner.

From which:

- A 14" Cedar scribed "CS-BT" bears N32°W, 46.4 feet.
- Scribe a 7" Douglas Fir "CS-BT" which bears S13½°W, 23.0 feet.

November 20, 1956  
C. Z. Boyden  
R. C. Elmgren

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT  
GCDB 640300**

Quarter corner common To Sections 24 and 25, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 4 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T36S R3E  
S24  
¼—  
S25  
1966

Bearing trees recorded on 1<sup>st</sup> Re-establishment in 1956, found with healed double blazes and measured to center at base:

- Fir, dead and down, brs. record; S 17° W, 23.1 ft.
- Cedar, now 22 ins. diam. brs. record; N 30° W, 46.9 ft.

Bearing trees recorded by the BLM in 1966, found with healed single blazes and measured to center at base:

- D. Fir, now 24 ins. diam. brs. record; N 66° E, 6.6 ft.
- Fir, dead and down brs. record; S 54° W, 23.8 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. Fir 6 ins. diam. brs. S 41° W, 38.1 ft.
- D. Fir 8 ins. diam. brs. S 46° E, 52.4 ft.

Corner lies approx. 900 ft. north of "Y" in spur roads.

May 1, 2012

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 176

V. – 16°