

FIRST RE-ESTABLISHMENT
GCDB 100300

Section corner common to Sections 19 and 30, Township 36 South, Range 4 West and Sections 25 and 30, Township 36 South, Range 5 West, W.M.

SEE RECORDED SURVEY NO. 3399

SECOND RE-ESTABLISHMENT

GCDB 100300

Section corner common to Sections 19 and 30, Township 36 South, Range 4 West and Sections 25 and 30, Township 36 South, Range 5 West, W.M.

The corner was perpetuated and recorded by Richard L. Templin, Josephine County Surveyor, in 1962, See Recorded survey No. 3399. It was set with a 30" long 1½" diam. iron pipe with a brass cap marked:

S24	S19
S25	S30
R5W	R4W
1962	

From original bearing trees with healed blazes:

- A Black Oak 22" diam. brs. N60½°E, 19 feet dist.
- A Black Oak 16" diam. brs. S60½°E, 38.5 feet dist.
- A Black Oak 22" diam. brs. N44°W, 40 feet dist.

From which new bearing trees:

- A Douglas Fir 12" diam. brs. S65°W, 15.6 feet dist. marked CS T36S R5W S25 BT with a 60d. pd. spike at base.

January 27, 1984
Witness: K. Mahoney

Richard L. Templin, L.S. 1354
Josephine County Surveyor

NOTE: SEE SURVEY NO. 9874

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 100300

Section corner common to Sections 19 and 30, Township 36 South, Range 4 West and Sections 24 and 25, Township 36 South, Range 5 West. W.M.

Found along North edge of 8x10 ins. stone, projecting 8 ins., containing notches on one edge and chiseled cross on top, the 1 ½ ins. diam. galvanized iron pipe, projecting 9 ins., with 3 ins. diam. brass cap marked:

COUNTY SURVEYOR

S24	S19
S25	S30
R5W R4W	
1962	

Set on Survey No. 3399, dated 1962. Add marks "C S 1987" to found brass cap.

Original bearing trees recorded by Ives & Hyde in 1854 found:

- Black Oak, 24 ins. diam. with healed blazes, leaning northerly, brs. Record: N61°E, 17.82 feet to estimated upper face. Re-measured, 17.4 feet to center of tree at lower blaze.
- Black Oak, 18 ins. diam. with healed blazes, brs. S62°E, 37.62 feet to estimated lower face. Record; S63°E. Re-measured, 38.04 feet to center of tree at lower blaze.
- The original southwest bearing tree is now gone.
- Black Oak, 23 ins. diam., now hollow at axed out and nearly re-healed upper face, brs. N44°W, 40.0 feet to center of tree at lower blaze. Record; N43°W, 39.60 feet.
- A found bearing tree, noted on Survey 9874, dated 1984, a Douglas Fir, 11 ins. diam., scribed "C.S." in partially healed upper face, brs. S66°W, 15.6 feet to center of tree at lower blaze. Record; S65°W.

Mark a new tree "CS" "BT":

- Douglas Fir, 13 ins. diam., brs. N48½°W, 25.70 feet to center of tree at lower blaze.

Corner lies on steep (55%) north slope, about 100 feet South of location marker on 8 ins. diam. fir, alongside irrigation canal.

July 29, 1987
R. Frost
S. Beecher

Edward McGinty
County Surveyor

V = 19°
P.-269