

## FIRST RE-ESTABLISHMENT

GCDB 100640


Quarter corner to Sections 1 & 6 Twp. 36 South, Ranges 4 & 5 West.

At the corner point I found a 3 ins. diam. by 3 feet high douglas fir post with aluminum tag affixed to the top marked "approximately  $\frac{1}{4}$  set from random line survey 5/6/71",

From which an original BT:

- Black oak snag 10 feet in. height bears S65°E, 7.9 feet dist.

At the corner point I set a 2 ins. G.I. pipe and brass cap marked:



From which new BTs:

- Douglas fir, 14 ins. diam., bears N49°E, 6.7 feet dist. marked "CS  $\frac{1}{4}$ S6 R5W BT".
- Douglas fir, 12 ins. diam., bears S12°W, 13.8 feet dist. marked "CS  $\frac{1}{4}$ S1 R5W BT".

December 3, 1973  
R. L. Templin, R.E. 3024  
Josephine County Surveyor

Witnesses: M. Ager  
W. Edwards