

## FIRST RE-ESTABLISHMENT

GCDB 200500

Section corner to Sections 7, 8, 17 & 18, Township 36 South, Range 4 West.

Found the stump of the original Southwest Fir witness tree with scribe marks plain. Also found the stump of the Southeast Fir witness tree with scribe marks plain on the down snag.

From said evidence, set a 2"x36" galvanized iron pipe with top 6" above the ground surface for corner.

From which:

- The face of the original witness tree (now a 30" Fir stump) bears South  $38\frac{1}{2}^{\circ}$  West, 19.1 feet;
- The face of the original witness tree (now an 18" Fir stump) bears South  $3^{\circ}$  East, 3.30 feet;
- Scribed a 4" Fir "CS-BT" which bears South  $35\frac{1}{2}^{\circ}$  West, 11.3 feet;
- Scribed a 3" Fir "CS-BT" which bears South  $35\frac{1}{2}^{\circ}$  East, 20.8 feet;
- Scribed a 6" Laurel "CS-BT" which bears North  $27\frac{1}{2}^{\circ}$  West, 30.9 feet.

September 1, 1959  
M. E. Boyden  
C. L. Birk  
F. Roberts

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 200500

Section corner common to Sections 7, 8, 17 and 18, Township 36 South, Range 4 West, W.M.

Found projecting 3 ins., the 2 ins. diam. iron pipe reported set on First re-establishment, page 16, in 1959. In the top of said pipe, set in concrete, a 2½ ins. diam. brass cap marked:

T36S R4W	
7	8
— —	
18	17
C.S.	
1986	

Original bearing trees marked by Chas. J. Howard in 1883 found:

- Fir stump, with scribed "T" visible in partial lower face, brs. S1¾°E, 3.30 feet. Record S6°E.
- Fir stump, with partial scribe marks visible in rotted upper and lower faces, brs. S38½°W, 19.1 feet to upper face. Record; S37°W.

Bearing trees marked on First re-establishment found:

- Fir, now 9 ins. diam. with double healed blazes, brs. Record: S35½°E, 20.80 feet to center of tree at lower blaze.
- Fir, now 11 ins. diam., with double healed blazes, brs. Record: S35½°W, 11.40 feet to center of tree at lower blaze.

Mk new tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Fir, 7 ins. diam., brs. N40½°E, 33.90 feet.

Corner lies at the Southeast corner of a clear-cut, on a 25% South-easterly slope, an estimated 100 feet East of a dirt road, course North-South.

November 18, 1986  
D. Edwards  
T. Newcomb

Edward McGinty  
County Surveyor

V = 17°

P. -315