

FIRST RE-ESTABLISHMENT

GCDB 340420

Center South Sixteenth corner to Section 16, Township 36 South, Range 4 West, W.M.

Found projecting 1 in., the 1 in. diam. iron pipe, origin unknown, with $\frac{5}{8}$ ins. diam. "marker" pipe, projecting 12 ins. alongside. Placed yellow plastic cap, marked

"Jackson C.S."

in the top of found 1 in. pipe.

To perpetuate this location, take references as follows:

- Place aluminum nail in blaze at the southwest side, near base, of a 5 ins. diam. White Oak, brs. $S58^{\circ}05'E$, 20.15 feet to nail head.
- Aluminum nail in blaze, at the northeast side, near base, of a 5 ins. diam. Douglas Fir, brs. $S15^{\circ}35'E$, 21.90 feet to nail head.

Corner lies about 38 feet Westerly of irrigation ditch at head gate. Fence line brs. north and old fence posts brs. east.

Note: Subject corner, used for the 1/16 corner in the past (see Survey No. 1708) is relegated to a "deed corner" and is perpetuated as such, as there exists two other probable positions for the center south one-sixteenth corner of Section 16.

For additional information concerning the origin of the above noted pipe and relation with other corners in Section 16, see Jackson County Project File 87-17 of survey in progress.

July 30, 1987
R. Frost, Tech.
S. Beecher, Tech.

Edward McGinty
County Surveyor

P. 287-288

SEE NEXT PAGE FOR IMPORTANT INFORMATION CONCERNING CORNER

FIRST RE-ESTABLISHMENT

GCDB 340420

Center South Sixteenth corner to Section 16, Township 36 South, Range 4 West, W.M.

Found the single bearing tree marked by previous County Surveyor James Jeffrey, on "Ancient Survey" No. 50, dated 1884, recorded on page 68, of County Surveyor's Record Vol. I, 1856-1913.

From the preceding evidence, set a $\frac{5}{8}$ x 24 ins. rebar, with yellow plastic cap marked "Jackson C.S.", from which;

- The above noted bearing tree, now an oak stump, 9 ins. diam. containing reverse impression of scribed "BT", brs. Record: S11°E, 14.52 feet to (reverse) scribed face.

To perpetuate this location, mark new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Cedar, 5 ins. diam., brs. N9°12'E, 31.84 feet.
- Ponderosa Pine, 11 ins. diam., brs. S73°14'E, 19.00 feet.
- A $\frac{5}{8}$ ins. diam. rebar, found flush, with yellow plastic cap marked "Jackson C.S." set on Jackson County Survey (in progress) brs. S69°26'28"W, 35.03 feet.
- A 1 in. diam. iron pipe, projecting 1 in., with yellow plastic cap marked "Jackson C.S.", noted on 1987 re-establishment as a monument "used" for the C.S. 1/16 corner in the past, brs. N82°06'56"W, 81.00 feet.

Note: The authority of this position's designation as the "true center south one-sixteenth corner is dependent on future resolution of the position of the center of Section 16. **SEE** Jackson County project file 87-17 of survey in progress.

Corner lies about 25.4 feet N66°30'E, of power pole No. "R1389" and 51 feet east of irrigation ditch.

August 16, 1987
R. Frost, Tech.
S. Beecher, Tech.

Edward McGinty
County Surveyor

P. -290