

FIRST RE-ESTABLISHMENT

GCDB 340440 (POSITION 1 OF 2)

Center quarter corner to Section 16 (Position 1 of 2), Township 36 South, Range 4 West, W.M.

Found projecting 1 ins., a 1 ins. diam. iron pipe; origin unknown. In the top of found pipe, set a yellow plastic cap marked "Jackson C.S."

To perpetuate this location, marked bearing trees "CS" "BT" and took measurements to center of trees at lower blaze:

- White Oak, 6 ins. diam., brs. S53°35'E 42.84 feet.
- White Oak, 6 ins. diam., brs. S61°19'W 43.40 feet.
- A found 5/8 ins. diam. rebar, flush, with yellow plastic cap, marked "Jackson C.S." set on Jackson County survey in progress, brs. S68°53'58"E 108.75 feet.

Corner lies about 100 feet west of the center of irrigation ditch and 3.3 feet, S60°E of wood post corner of south and east bearing fence lines.

Note: Subject corner "used" for the center of the section in the past (see Survey No. 2512) is relegated to a "deed corner" and is perpetuated as such, as there exists two other probable positions for the center of Section 16.

For additional information concerning the origin of the above noted pipe and relation with other corners in Section 16.

See Jackson County Project File 87-17.

July 30, 1987
R. FROST, Tech III
S. BEECHER, Tech I

Edward McGinty
County Surveyor

P. 286-287

FIRST RE-ESTABLISHMENT

GCDB 340440 (POSITION 2 OF 2)

Center Quarter corner to Section 16 (Position 2 of 2), Township 36 South, Range 4 West, W.M.

Found the single bearing tree, marked by previous Jackson County Surveyor Jas. Jeffrey, on "Ancient Survey" No. 50, dated 1884, recorded on page 68, of County Surveyor's Record, Vol. I, 1856-1913.

From the preceding evidence, set a $\frac{5}{8}$ x 24 ins. rebar, 23 ins. in the ground, with a yellow plastic cap marked "Jackson C.S.", from which,

- The above noted bearing tree, now an oak snag, 18 ins. diam., containing scribed "s" and "BT" in opened faces, brs. Record: N20°E 21.12 feet to scribed lower face.

To perpetuate this location, marked new trees "CS" "BT" and took measurements to center of trees at lower blaze:

- Douglas Fir, 5 ins. diam., brs. N22°53'E 24.25 feet.
- The east branch, 6 ins. diam., double Black Oak, brs. S54°35'W 22.07 feet.
- A found $\frac{5}{8}$ ins. diam. rebar, flush, with yellow plastic cap, marked "Jackson C.S.", set on Jackson County survey (in progress) brs. S6°56'19"W 37.27 feet.
- A found 1 ins. diam. iron pipe with yellow plastic cap marked "Jackson C.S.", noted on above 1987 re-establishment as a monument "used" for the center of section in past years, brs. N88°50'08"W 105.98 feet.

Note: Subject corner monument, the position of which was determined by previous County Surveyor Jas. Jeffrey in 1884, is currently in conflict with the theoretical center of section, based on extant quarter corners of Section 16.

Its position is perpetuated in anticipation of future resolution of it's legal significance relative to the "true" center of Section 16.

SEE ALSO Jackson County project file 87-17 of survey in progress.

Corner lies 6.7 feet East of irrigation ditch and 4 feet south of east-west fence line.

August 6, 1987
R. Frost, Tech III
S. Beecher, Tech I

Edward McGinty
County Surveyor

P.-289