

**FIRST RE-ESTABLISHMENT**

**GCDB 440100**

South quarter corner to Section 34, Township 36 South, Range 4 West, W.M.

Found witness tree for this corner in Section 3, Township 37 South, Range 4 West, from which I set corner and marked with a 4" squared post, scribed  $\frac{1}{4}S$

Also found stump hole corresponding to the location of other original tree.

Set an 8" black oak which bears  $N60\frac{1}{2}^{\circ}E$ , 79.0 feet.

January 23, 1914  
A. T. Brown,  
Deputy County Surveyor

H. Ling, Chainman  
C. Boyden, Chainman

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

GCDB 440100

Quarter corner common to Sections 34, Township 36 South, Range 4 West and Section 3, Township 37 South, Range 4 West.

Set 1"x36" galvanized iron pipe 36" in the ground with 2½" bronze cap stamped:

T36&37SR4W  
34  
¼S — COR  
3  
C.S.  
1967

From which:

- The original Black Oak now 25" with lower blaze intact, bears South 53° West, 5.9 feet to the face of the upper blaze;
- The Black Oak marked on the first re-establishment, now cut with "¼ S" scribe visible, replaced trunk on stump which bears North 60¼° East, 79.2 feet to the upper face.
- A stump of the Black Oak marked on Recorded Survey No. 2663 with scribe 404-BT bears North 59½° East, 78.2 feet;
- A pulley wheel, reported as a pipe on Survey No. 2662, bears North 71° West, 3.98 feet;
- A 1½" pipe bears North 56½° West, 0.50 feet.

Marked the following new trees:

- An 8" Black Oak scribed CS-BT bears South 39¼° West, 38.1 feet to the face of the lower blaze;
- An 8" White Oak scribed CS-BT bears South 33¾° East, 40.1 feet to the face of the upper blaze.

October 18, 1967  
F. A. Roberts  
Jack Huston

Approved By:  
L. D. Pinkham  
Deputy County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT**

**GCDB 440100**

Quarter corner common to Section 34, Township 36 South, Range 4 West and Section 3, Township 37 South, Range 4 West, W.M.

Found flush, the 2½ ins. diam. brass cap marked:

T36&37S R4W  
34  
¼S — cor.  
3  
C.S.  
1967

Reported set in a 1x36 ins. iron pipe on second re-establishment, page 23, in 1967.

Original bearing tree marked by Ives and Hyde in 1854 found:

- Black Oak, now 26 ins. diam. with rotted upper face, brs. Record: S53°W, 5.94 feet to estimated position of said face.

Bearing trees marked on said second re-establishment found:

- White Oak, now 11 ins. diam. with double healed blazes, brs. Record: S33¾°E, 40.1 feet to estimated upper face. Re-measured 40.34 feet to center of tree at lower blaze.
- Black Oak stump, supporting live growth, brs. Record: S34¼°W, 38.3 feet to center of stump.

Take new references as follows:

- White Oak, 7 ins. diam. scribed "CS" "BT" brs. S24½°W, 38.52 feet to center of tree at lower blaze.
- The most easterly Southeast corner of the block foundation of a wood frame house at 1788 Birdseye Cr. Rd. brs. N59¼°W, 40.86 feet.

Corner lies 6.7 feet North of an East-West chain link fence and 6.5 feet South of the middle of an East-West gravel driveway to said house.

November 25, 1986  
D. Edwards  
R. Romio

Edward McGinty  
County Surveyor

V = 19½°  
P. -336

**SEE NEXT PAGE FOR FOURTH RE-ESTABLISHMENT**

## FOURTH RE-ESTABLISHMENT

GCDB 440100

Quarter corner common to Section 34, Township 36 South, Range 4 West and Section 3, Township 37 South, Range 4 West, W.M.

Found flush and broken in half the brass cap set on second re-establishment, in 1967.

Replaced monument with a 1x36 ins. galvanized iron pipe 39 ins. in the ground with a 2½ ins. brass cap marked:

T36S&37S R4W  
34  
¼S —  
3  
C.S.  
1992

- Single remaining bearing tree reported by Ives and Hyde in 1854 found; a Black Oak, 28 ins. diam., with rotted upper face brs. Record: S53°W, 5.94 feet to estimated face.
- Single remaining bearing tree marked on second re-establishment, a Black Oak with healed blazes brs. Record: S33¾°E, 40.10 feet to estimated face. Re-measured 40.24 feet to center.
- Bearing tree marked on third re-establishment found; White Oak 7 ins. diam., with partially healed blaze, brs. Record: S24½°W, 38.52 feet to center of lower blaze.
- Pulley brs. record (second re-establishment) N71°W, 3.98 feet 1½ ins. iron pipe, now bent over, brs. N56½°W, .70 feet. Record (second re-establishment) .50 feet.

Corner lies on South edge of graveled driveway bearing east and west and 6½ feet north of a 6 foot high cyclone fence.

April 14, 1992  
T. Newcomb, Tech.  
H. Durkee, Tech.

Verlyn Thomas  
County Surveyor

V = 18½°  
P. -20