

FIRST RE-ESTABLISHMENT

GCDB 440600

Quarter corner common to Sections 3 and 10, Township 36 South, Range 4 West, W.M.

Set a 1x36" galvanized iron pipe 33" in the ground in a mound of rock with a 2½" bronze cap stamped:

T. 36 S. R. 4 W.
3
¼S — Cor.
10
C.S.
1971

For corner, from which:

- The original bearing tree (now a 24" Sugar Pine snag, plainly scribed "¼ S-BT") bears N 10° W, 10.0 feet to the center;
- The original bearing tree (now an Oak stump hole) bears S 10° E, 31 feet.

Establish new bearing trees as follows:

- A 12" Black Oak, scribed "CS-BT" bears S 15½° E, 50.7 feet to the face of the lower blaze;
- An 11" Douglas Fir, scribed "CS-BT" bears N 73¾° W, 40.9 feet to the face of the lower blaze.

May 18, 1971
Otis Blankenship
Dan Phillips

Approved by:
Mark E. Boyden
Jackson County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 440600

Quarter corner common to Sections 3 and 10, Township 36 South, Range 4 West, W.M.

Found monument set on first re-establishment, in 1971, pulled out of the ground. Reset found monument, a 1x36 ins. galvanized iron pipe, 18 ins. in the ground with a 2½ ins. diam. brass cap marked:

T36S R4W
3
¼S —
10
C.S.
1971

Bearing Trees marked on first re-establishment found with healed blazes:

- Douglas Fir, 17 ins. diam., brs. Record: N73½°W, 40.90 feet to estimated face. Re-measured; 41.19 feet to center.
- Black Oak, 15 ins. diam., brs. Record: S15½°E, 50.70 feet to estimated face. Re-measured; 51.10 feet to center.

Unrecorded bearing tree found:

- Black Oak, 9 ins. diam., with healed blazes, brs. N3°E, 28.45 feet to center at lower blaze.

Mound stones around corner and marked new bearing tree "CS" "BT":

- Madrone, 8 ins. diam., brs. S83°W, 23.50 feet to the center of tree at lower blaze.

Corner lies 25 feet North of small spur course slopes west and on north slope.

October 20, 1993
T. Newcomb, Tech.
J. Hawkinson, Tech.

Verlyn Thomas
County Surveyor

V = 18°

P.-153