

FIRST RE-ESTABLISHMENT

GCDB 540200

Quarter corner common to Sections 26 and 35, Township 36 South, Range 4 West, W.M.

Set 2"x36" gas pipe ½ foot below surface of the ground,

From which

- A 22" White Oak bears South 57°50' East, 80.4 feet.

Scribe CS-BT a 17" White Pine bears North 36°35' East, 261.0 feet.

November 22, 1927
Boyden, Deputy County Surveyor
R. Smith and R. Kent, Chainmen

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 540200

Quarter corner common to Sections 26 and 35, Township 36 South, Range 4 West, W.M.

Found the 2" iron pipe 9" deep, as set for corner by Deputy County Surveyor, C. Z. Boyden on November 22, 1927.

Set a 1"x36" galvanized iron pipe inside said 2" iron pipe, 39" in the ground with a 2½" bronze cap stamped:

T. 36 S. R. 4 W.
26
¼S — Cor.
35
C.S.
1971

From which:

- The First re-establishment bearing tree (now a 26" White Oak with healed blazes) bears S 62° E, 81.3 feet to the center of the tree (record = S 57° 50' E, 80.4 feet to the face)
- The Southeast corner of the concrete foundation for a one-story wood-frame residence bears N 25° 07' E, 207.2 feet.

November 12, 1971
Gary Kaiser, Deputy County Surveyor
Lloyd Shreeve

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

GCDB 540200

One Quarter corner common to Sections 26 and 35, Township 36 South, Range 4 West, W.M.

At the corner found 2 ins. deep, the 1 ins. diam. iron pipe with 2½ ins. diam. brass cap marked:

T36S R4W
26
qtr Cor.
35
C.S.
1971

Set on Second Re-establishment, in 1971.

A bearing tree recorded on Second Re-establishment,

- A White Oak, now 28 ins. diam. with healed blazes, located on East edge of lane, at the top of east slope of Footh Creek, bears record, S62°E (basis of bearing) 81.3 feet to center of tree at lower blaze.

I set new references; 5/8 x 30 ins. rebars, flush with the surface of the ground, with yellow plastic caps marked: "JACKSON C.S." as follows;

- S62°E, 67.91 feet located at West side of lane on North-South fence line.
- N62°W, 36.89 feet located on North-South fence line.

Corner lies in fenced pasture.

June 4, 1980
R. Frost
D. Danielsen

Approved by: Edward McGinty
County Surveyor