

FIRST RE-ESTABLISHMENT

GCDB 700140

Quarter corner common to Section 36, Township 36 South, Range 4 West and Section 31, Township 36 South, Range 3 West, W.M. $V = 20^\circ$

From the following evidence, at the location described below, I set a 1x36 ins. G.I. pipe 30 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1975
T36S
¼S
36 | 31
R4W R3W

Original BTs recorded by Ives and Hyde in 1854, found as follows:

- Sawed Fir stump, 30 ins. diam., scribed "BT", bears record $S44^\circ E$, 11.22 feet to scribed face.
- Fir, 27 ins. diam., with burned out lower and healed upper face, bears Record: $N26^\circ W$, 32.34 feet (on slope) to estimated upper face. Re-measured, 30.9 feet to center of tree.

I marked the following new trees C.S. BT and take measurements to center of trees at lower blaze:

- Black Oak, 4 ins. diam., bears $S12\frac{1}{2}^\circ E$, 27.63 feet.
- Douglas Fir, 7 ins. diam., bears $S68\frac{1}{2}^\circ W$, 54.20 feet.

Corner lies about 200 feet South of ravine on the S.E. cut slope of old skid road.

December 22, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor