

## FIRST RE-ESTABLISHMENT

GCDB 140400

Quarter corner common to Section 18 and 19, Township 38 South, Range 1 West, W.M.

At the corner found re-bar,  $\frac{5}{8}$ -inch diameter, 9 inches below surface of asphalt road. (Origin unknown).

Directly over said re-bar, set 2½-inch diameter brass cap in concrete, flush, marked:

T38S R1W  
18  
¼S —  
19  
C.S.  
1981

References taken by Jackson County (See "Corners for Control Points in Danger by Construction" book pg. 12, 1969) found:

- Iron pipe,  $\frac{3}{4}$ -inch diameter, 4 inches deep on E-W fence line bears Record:  $S0^{\circ}09'E$ , 21.49 feet.
- White Oak, 19-inch diameter, with healed single blaze bears Record:  $S71^{\circ}30'E$ , 82.3 feet to center of tree.

Set new reference:

- Aluminum 8d nail in South side pear tree, 11-inch diameter, bears  $N20^{\circ}W$ , 56.38 feet.
- Re-bar,  $\frac{5}{8}$ -inch diameter, 30 inches long, with yellow plastic cap marked "Jackson CS" flush on East-west fence line, bears  $N0^{\circ}09'W$ , 37.81 feet. SEE ALSO Survey No. 2116.

Corner lies about 10 feet South of middle Dark Hollow Road.

April 16, 1981  
R. Frost  
R. Templin

Edward McGinty  
County Surveyor

P. -65

$V = 19\frac{1}{2}^{\circ}$

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 140400

Quarter corner common to Section 18 and 19, Township 38 South, Range 1 West, W.M.

Found re-bar,  $\frac{5}{8}$  ins. diam., 9 ins. below surface of asphalt road, (origin unknown). Brass cap set on the First Re-establishment, dated 1981, missing.

Directly over found re-bar, set a 1 x 9 ins. section of galvanized iron pipe in cement with  $2\frac{1}{2}$  ins. diam. brass cap marked:

JACKSON COUNTY SURVEYOR  
T38S R1W  
18  
 $\frac{1}{4}$ S —●—  
19  
2011

Cemented in top flush with asphalt surface.

References recorded on the first Re-establishment found and tied using a new bearing basis, being the line between this corner and the brass capped Southeast Corner to Donation Land Claim 51, N89°34'36"E per the First Re-establishment, dated 1995, of that corner.

- Iron pipe,  $\frac{3}{4}$  ins. diam., 4 ins. deep on E-W fence line, bears S0°37'25"E, 21.51 ft. Record S0°09'E, 21.49 ft.
- Yellow plastic cap, cracked with "JACKSON C.S." visible, bears N0°34'53"W, 37.80 ft. Record N0°09'W, 37.81 ft.

New references:

- $\frac{5}{8}$  x 24 ins. rebar with 2 ins. diam. aluminum cap marked:

JACKSON COUNTY  
  
SURVEYOR

Flush with ground bears N70°48'42"W, 102.36 ft. Located 3 ft. South of East-West fence on North side of Dark Hollow Rd.

- $2\frac{1}{2}$  ins. diam. brass cap, the Southeast Corner to Donation Land Claim No.51, bears N89°34'36"E, 837.06 ft. Cap is flush with the asphalt and located near the middle of the East bound lane of Dark Hollow Rd.

Corner is located in the East bound lane of Dark Hollow Rd.,  $1\frac{1}{2}$  ft North of the South edge of pavement.

April 14, 2011  
S. Beecher  
S. Fein

Kerry K. Bradshaw  
County Surveyor

P. 66-67

**SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT**

## THIRD RE-ESTABLISHMENT

GCDB 140400

Quarter corner common to Section 18 and 19, Township 38 South, Range 1 West, W.M.

Found the 2½ ins. diam. brass cap per Second Re-Establishment, dated 2011, cemented flush in asphalt and marked:

JACKSON COUNTY SURVEYOR  
T38S R1W  
18  
¼S —●—  
19  
2011

References recorded on the Second Re-establishment found;

- Iron pipe, ¾ ins. diam., 2 ins. deep on E-W fence line, bears S 0°50'33" E, 21.48 ft. Record S 0°37'25" E, 21.51 ft.
- 5/8 ins. diameter rebar with no cap, bears N 0°49'59" W, 37.79 ft. Record N 0°34'53" W, 37.80 ft.
- 5/8 x 24 ins. rebar with 2 ins. diam. aluminum cap marked:

JACKSON COUNTY  
  
SURVEYOR

Flush with ground bears N 71°05'51" W, 102.32 ft. Record N 70°48'42" W, 102.36 ft. Located 3 ft. South of East-West fence on North side of Dark Hollow Rd.

- 2½ ins. diam. brass cap, the Southeast Corner to Donation Land Claim No.51, bears N 89°15'43" E, 837.06 ft. Record N 89°34'36" E. Cap is flush with the asphalt and located near the middle of the East bound lane of Dark Hollow Rd.

Set new reference;

- 5/8 x 24 ins. rebar with 2 ins. diam. aluminum cap marked "Jackson County Surveyor" exposed 1 ins. bears S 88°27'33" E, 255.17 ft. located in the center of the southerly ditch along Dark Hollow Road and +/- 150 feet westerly of the driveway for residence 7017

Basis of Bearing: NAD 83 2011 Epoch (2010) OCRS GP/ASH zone per OAR 734-005-0015

Corner is located in the East bound lane of Dark Hollow Rd., 1½ ft North of the South edge of pavement and +/- 200 feet Easterly of the driveway for residence number 6913

January 16, 2020  
J. Hall  
O. Ribanszky

Scott D. Fein  
County Surveyor