

FIRST RE-ESTABLISHMENT

GCDB 340440

Center Quarter Corner to Section 16, Township 38 South, Range 1 West, W.M.

Found 10 inches deep, the $\frac{1}{2}$ x 2 inches iron bar, apparently set on Hillsinger Subdivision, in 1922. Directly over found pin, flush with the asphalt surface of Camp Baker Road, set a $2\frac{1}{2}$ -inch diameter brass cap in concrete, marked:

T38S R1W

C $\frac{1}{4}$

.

C.S.

1987

A found iron pin, $\frac{3}{4}$ -inch diameter set on 1940 Jackson County Road Survey, bears North, 20.0 feet.

To perpetuate this location, set a $\frac{5}{8}$ x 24-inch rebar, 2 inches deep, with yellow plastic cap marked: "Jackson C.S.", located on North-South fence line (14 feet South of North end), bears South, 34.30 feet.

Corner lies in the middle of Camp Baker Road, $S79^{\circ}47'E$, 115.42 feet from the center of Power Pole No. D-7630.

January 23, 1987
David Edwards
Roberta Romio

Edward McGinty
County Surveyor

P.-20