

**FIRST RE-ESTABLISHMENT**

**GCDB 640400**

Quarter corner common to Sections 13 and 24, Township 38 South, Range 1 West.

Set 8 x 12 x 18 inches sand stone with X on top, 1 foot below surface of ground, also, drove ¼" gas pipe which stands 1 foot aboveground

One foot East of X on stone, found remains of old cedar stake; also, checked distance East and West.

October 23, 1923  
C. Z. Boyden,  
Deputy County Surveyor

A. Schoenberger, Chainman

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

GCDB 640400

Quarter corner common to Sections 13 and 24, Township 38 South, Range 1 West, W.M.

Found 10 inches deep, brass cap, in concrete marked:

T38S R1W  
13  
¼S — Cor.  
24  
C.S.  
1972

The only recovered record of this monument is found in field book, Reconnaissance Notes, which states subject brass cap was set "over" found sandstone with cross.

The identification of this stone, to be the same as that reported on First Re-establishment, in 1923 is further confirmed in 1972, by a "beat-up pipe on East side". This pipe, or a section thereof, now 1x18 inches and bent, is found laying on top the ground a few feet East of the brass cap.

To perpetuate this location, take new references:

- Chiseled cross in approximate center of a 3 x 6 x 1.5 feet high boulder, located about 10 feet Northerly of angle point in irrigation ditch, bears N85°55'E, 9.62 feet.
- Chiseled cross atop the Southeast (outlet) end of a 12-inch diameter concrete culvert, bears S7°06'E, 13.74 feet.
- A ¾-inch diameter rebar, found flush, being triangulation point "No. 36" noted Survey No. 5011, bears S3°01'W, 774.86 feet.

Corner lies about 20 feet East of gravel road c. North-south and approximately 15 feet South of orchard road c. East along North side of irrigation ditch.

February 5, 1985  
R. Frost  
E. McGinty

Edward McGinty  
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

SPECIAL CORNER

THIRD RE-ESTABLISHMENT

GCDB 640400

Quarter corner common to Sections 13 and 24, Township 38 South, Range 1 West, W.M.

Found at the corner position, 12 inches deep, the brass cap in concrete recorded on Second Re-establishment in 1985, marked:

T38S R1W  
13  
¼S — COR  
24  
C.S.  
1972

All references recorded on said Second Re-establishment either destroyed by road construction or are now inaccessible due to new 8-10 feet high fence.

Set new references, 5/8 x 24-inch rebar with 1½-inch diameter aluminum caps marked



Bears:

- N1°16'07" W, 174.26 feet. Set 0.1 foot deep.
- N12°46'30" W, 156.01 feet. Set 0.1 foot deep.
- N61°19'24" E, 17.77 feet. Set flush.

Brass cap set in concrete for Section corner common to Sections 13 and 24 of Range 1 West, and Sections 18 and 19 of Range 1 East, Township 38 South, W.M. bears S 89°40' E, 2643.02 feet.

Corner lies near east edge of granite road and 3 feet north of north end of 10-foot high fence at angle point northeasterly.

September 10, 2003

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. - 136