

FIRST RE-ESTABLISHMENT

DLC47ESE

GCDB 200577

West Southwest corner of DLC #46, Township 38 South, Range 1 West, Also East Southeast of DLC #47, Township 38 South, Range 1 West.

- Found the 1" capped pipe with cross on top as set for corner by the engineering firm of Osgood and Cummings in 1910.
- Chiseled a cross on the Northeast corner of a concrete irrigation diversion box which bears South $40\frac{3}{4}^{\circ}$ West, 10.78 feet;
- Chiseled a cross on the Southwest corner of a concrete irrigation diversion box which bears North $71\frac{3}{4}^{\circ}$ East, 34.27 feet;

The center of an 8" pear tree bears South $57\frac{1}{2}^{\circ}$ East, 23.0 feet.

February 9, 1959
M. E. Boyden
L. D. Pinkham

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

DLC47ESE

GCDB 200577

West Southwest corner DLC No. 46, Located in Section 8, Township 38 South, Range 1 West, W.M. (Also the East Southeast corner of DLC No. 47)

Found, 6 inches deep the 1-inch diameter iron pipe with 1½-inch diameter cap marked with cross, recorded as the corner of First re-establishment in 1959.

References recorded on First re-establishment found as follows:

- A chiseled cross on the Southwest corner of a concrete irrigation box bears record N71°45'E, 34.27 feet.
- A chiseled cross on the Northeast corner of a concrete irrigation box bears S40°45'W, (basis of bearing), 10.74 feet. Record: S40¾°W, 10.78 feet
- Recorded pear bearing tree now gone.

I set new references: 5/8 x 30-inch rebars with yellow plastic cap marked "Jackson C.S.", flush with the ground, bears:

- S59°11'E, 21.15 feet located 18 inches Northwesterly of a 7-inch diameter pear tree.
- N37°16'W, 112.50 feet located at the Southeast corner of a wood frame residence.

June 24, 1980

R. Frost

D. Danielsen

Witnesses: Paul Lewis and Cliff Birk

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

THIRD RE-ESTABLISHMENT

DLC47ESE

GCDB 200577

West Southwest corner to Donation Land Claim No. 46 also being the East Southeast corner to Donation Land Claim No. 46, located in Section 8, Township 38 South, Range 1 West, W.M.

Found the 1-inch diameter iron pipe, with 1½-inch diameter water cap marked with an "X" on top and 6 inches below ground surface, recorded as the corner on the First Re-establishment, dated 1959.

Removed found pipe and set a 1x 36-inch Galvanized iron pipe with 2½-inch diameter brass cap marked:

T38S R1W
ESE WSW
47 | 46
—
CS
1990

Cemented in the top 9 inches below ground surface from which, references marked on the First Re-establishment found:

- Chiseled cross on the Southwest corner of a concrete irrigation box bears N72°E, 34.25 feet. Record: N71¾°E, 34.27 feet.
- Chiseled cross on the Northeast corner of a concrete irrigation box bears S41°W, 10.78 feet. Record: S40¾°W, 10.78 feet.

References set on the Second Re-establishment, dated 1980, found:

- 5/8-inch diameter rebars with yellow plastic caps marked "Jackson C.S." flush with the ground:
- 1.5 feet Northwest of an 8-inch diameter pear tree, bears S59°E, 21.15 feet. Record: S59°11'E, 21.15 feet.
- At the Southeast corner of a wood frame residence, bears N37¼°W, 112.55 feet. Record: N37°16'W, 112.50 feet.

Corner lies at the outside edge of 90° curve in a dirt road through pear orchard and 3 feet East of Power Pole No. D6642.

March 8, 1990
S. Beecher, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 17°
P. -50