

## FIRST RE-ESTABLISHMENT

### GCDB 100640

Quarter corner common to Section 1, Township 39 South, Range 3 East, and Section 6, Township 39 South, Range 4 East, W.M.  $V = 20\frac{1}{4}^\circ$

Found, squared wooden post, which I replaced with a 1 x 36-inch Galvanized iron pipe set 24 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975  
T39S R4E  
¼S  
1 | 6  
R3E R4E

Original BTs recorded by S. Truax in 1859 found as follows:

- The stump, 16-inch diameter, scribed "BT", of a down and rotted Fir, containing scribed "S", bears record, S88°W, 5.94 feet to scribed face.
- A stump hole found at record location of original SE BT.

I mounded stones around corner, marked new trees CS BT and took measurements to center of trees at lower blaze:

- Cedar, 24-inch diameter bears S77½°E, 45.23 feet.
- White Fir, 16-inch diameter bears S27½°W, 21.32 feet.

Corner lies about 725 feet South of top of spur, on blazed North-South line.

September 15, 1975  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor