

FIRST RE-ESTABLISHMENT

GCDB 200240

Quarter corner common to Section 30 only, Township 39 South, Range 4 East, W.M. $V = 18\frac{1}{4}^\circ$

I replaced a rotted wood stake, in mound of stone, with a 1 x 36-inch Galvanized iron pipe set 24 inches in the ground (leaning 15° NE) with a 2½-inch bronze disc marked:

Jackson County 1975
T39S R4E
¼S 30 |

Original BTs recorded by S. Truax in 1859, found as follows:

- A sawed Pine stump, 30-inch diameter, scribed "T" in partially exposed lower face bears Record: $S60^\circ E$, 20.46 feet to scribed face.
- A sawed Pine stump, 48-inch diameter, containing scribed partial "BT" in opened lower face, bears Record: $N39^\circ W$, 73.26 feet to scribed face.
- Found among stones mounded around corner, one comparable in size, (12 x 8 x 8 ins.) with that recorded as being set by P. Applegate in 1893. However no markings were visible.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Cedar, 14-inch diameter bears $S29^\circ E$, 19.03 feet.
- Cedar, 7-inch diameter bears $N20\frac{1}{2}^\circ W$, 25.38 feet.

Corner lies on blazed North-South line in bottom of small stream bed.

August 6, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor