

FIRST RE-ESTABLISHMENT

GCDB 200540

Quarter corner common to Sections 7 and 8, Township 39 South, Range 4 East, W.M. $V = 22^\circ$

From the following evidence, at the location described below, I set a 1 x 36-inch Galvanized iron pipe 26 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T39S R4E
¼S
7 | 8

Original BTs recorded by S. Truax in 1859, found as follows:

- A Fir snag, 20-inch diameter, scribed "B" in partially exposed face bears Record: N80°W, 29.70 feet.
- The stump hole of a down Fir, 28-inch diameter bears Record: S21°E, 36.30 feet.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas Fir, 15-inch diameter bears S73½°E, 44.55 feet.
- Douglas Fir, 10-inch diameter bears S14½°W, 34.74 feet.

Corner lies S43°W, about 350 feet from the end of rip-rapped road on East edge of small reservoir.

September 8, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor