

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 3 AND 4 ONLY
GCDB 400700**

Closing corner common to Sections 3 and 4, Township 39 South, Range 4 East, W.M. $V = 20^\circ$

Found, firmly set, the original stone, marked as recorded by P. Applegate in 1893, with punch mark on top.

I replaced said stone with a 1 x 36-inch Galvanized iron pipe set 30 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T38S R4E
34
—|—
4 | 3
C.C.
T39S

From which, a decomposed Fir stump bears record, $S29^\circ W$, 56.1 feet.

- A stump hole found at record location of original NW BT.

I mounded stones around corner, deposited original stone alongside as a memorial, marked new trees CS BT and took measurements to center of trees at lower blaze:

- Douglas Fir, 10-inch diameter bears $S12\frac{1}{4}^\circ E$, 33.5 feet.
- Douglas Fir, 8-inch diameter bears $S72\frac{1}{2}^\circ W$, 21.15 feet.
- The standard corner of Sections 33 and 34, (T38S) bears $N87^\circ 20' 10'' W$, 40.70 feet as recorded on Survey No. 3896, dated 1968. Original record, West, 40.26 feet.

Corner lies about 50 feet West of road.

September 3, 1975
Ed Graham
B. Malotte

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 3 AND 4 ONLY
GCDB 400600**

Closing corner common to Sections 3 and 4 in Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 1 inch and in a mound of stones, the 1-inch diameter galvanized iron pipe with a 2½-inch diameter brass cap set on First Re-establishment in 1975, marked:

JACKSON COUNTY 1975
T38S R4E
34
—|—
4 | 3
C.C.
T39S

References recorded on said First Re-establishment, found and re-measured:

- Sawed fir stump bears Record: S12¼°E, 33.5 feet to center.
- Standard corner monument for Sections 33 and 34, T38S bears Record: N 87° 20'W, 40.70 feet.

Take new references:

- White Fir, 9-inch diameter, scribed "CS" "BT" bears S53°W, 50.8 feet to center at lower blaze.
- Set a 5/8 x 24-inch rebar with a 1½-inch diameter bronze cap, exposed 2 inches and marked:

JACKSON COUNTY

SURVEYOR

At base of sawed bearing tree stump: S12°E, 32.7 feet.

Corner lies approximately 50 feet west of graveled road in an area recently disturbed by logging activity.

April 23, 2007
H. Durkee
B. Beeman

Roger R. Roberts
Jackson County Surveyor

P. - 102
V. - 16°50'