

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 11 ONLY
GCDB 500538**

West Quarter corner to Section 11 only, Township 39 South, Range 4 East, W.M. $V = 17^\circ$

From the following evidence at the location described below, I set a 1 x 36-inch Galvanized iron pipe 20 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T39S R4E
¼S | 11

Original BTs recorded by P. Applegate in 1893, found as follows:

- The stump remains of a down and rotted Fir, about 20-inch diameter bears record: $S63^\circ W$, 23.76 feet to estimated face.
- Ponderosa Pine stump remains bear record, $S70^\circ E$, 12.54 feet.

Corner lies in skid trail, original stone not found.

I mounded stones around corner, marked new trees CS BT, and took measurements to center of trees at lower blaze:

- Ponderosa Pine, 15-inch diameter bears $N89^\circ E$, 16.37 feet.
- Ponderosa Pine, 9-inch diameter bears $N57^\circ W$, 5.90 feet.
- The East ¼ corner of Section 10 bears North, 56.10 feet.

Corner lies about 600 feet North of location marker on 8-inch diameter Ponderosa Pine, near point of ridge, alongside road.

September 2, 1975
B. Malotte
R. Frost

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND REESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 500538

West Quarter corner of Section 11 only, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 12 inches in a mound of stones, the 1-inch diameter galvanized iron pipe with a 2½-inch diameter brass cap set on 1st Re-establishment in 1975, marked:

Jackson County 1975
¼S | 11

Single remaining original bearing tree recorded by Peter Applegate of the GLO in 1893, rotted fir remains bears record; S 63° W, 23.8 feet to middle of stump hole.

Bearing tree recorded on said 1st Re-establishment, found with healed double blazes and measured to center at lower blaze:

- Ponderosa pine, 33-inch diameter bears record; N 89° E, 16.4 feet.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- Cedar 12-inch diameter bears S 51½° E, 19.5 feet.

Corner lies approximately 500 feet east of a cinder road.

November 4, 2010
H. Durkee

Kerry Bradshaw
Jackson County Surveyor

V. – 13°10'
P. – 220