

## FIRST RE-ESTABLISHMENT

GCDB 600140

Quarter corner common to Sections 35 and 36, Township 39 South, Range 4 East, W.M.  $V = 19^\circ$

From the following evidence at the location described below, I set a 1 x 36-inch Galvanized iron pipe 26 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975  
T39S R4E  
¼S  
35 | 36

Original BTs marked by S. Truax in 1859, found as follows:

- A sawed Sugar Pine stump, 32-inch diameter, scribed "BT" in opened lower face bears  $S49^\circ E$ , 63.01 feet to marked face. Record,  $S49^\circ E$ , 62.70 feet.
- A sawed Fir stump, 50-inch diameter, containing axed chaining notch and scribed "4" and "BT" in opened faces bears  $N58^\circ W$ , 53.11 feet to marked lower face. Record:  $N58^\circ W$ , 52.80 feet.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- White Fir, 14-inch diameter bears  $N9^\circ E$ , 5.90 feet.
- Douglas Fir, 12-inch diameter bears  $N81^\circ W$ , 10.34 feet.

Corner lies about 630 feet West of location marker on 8-inch diameter, Ponderosa Pine, alongside road.

August 19, 1975  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 600140

Quarter corner common to Sections 35 and 36, Township 39 South, Range 4 East, W.M.

Found at the corner position, exposed 10 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set on 1<sup>st</sup> Re-establishment in 1975 marked:

JACKSON COUNTY 1975  
T39S R4E  
¼S  
35 | 36

Single remaining original bearing tree recorded by S. Truax of the GLO in 1859, a rotted fir stump brs. record; N 58° W, 53.1 ft. to center.

Bearing trees recorded on said 1<sup>st</sup> Re-establishment found and measured to center at lower blaze:

- Fir high-stump with healed double blazes brs. record; N 9° E, 5.9 ft.
- Sawed fir stump with "BT" in exposed lower face brs. record; N 81° W, 10.3 ft.

Mark new bearing trees "CS" "BT" and take measurements to center at lower blaze:

- W. fir 10 ins. diam. brs. N 76¼° E, 47.2 ft.
- W. fir 9 ins. diam. brs. S 23¼° E, 76.4 ft.
- D. fir 4 ins. diam. brs. S 39° W, 5.7 ft.
- No trees of size in northwest quadrant.

Corner lies approx. 600 ft. west of cinder road.

September 18, 2008

H. Durkee

B. Beeman

Roger R. Roberts

Jackson County Surveyor

P. – 185

V. – 15°35'