

## FIRST RE-ESTABLISHMENT

GCDB 600300

Section corner common to Sections 23, 24, 25 and 26, Township 39 South, Range 4 East, W.M.

Found at the corner position, flush in a ring of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T39S R4E	
S23	S24
— —	
S26	S25
1966	

Single remaining original bearing tree recorded by S. Truax of the GLO in 1859,

- The core of a Pine stump, brs. record; N 20° E, 40.9 ft. to estimated face.

Bearing trees recorded by the BLM in 1966, found with healed single blazes and measured to center at base:

- W. Fir, now 21 ins. diam. brs. N 14° E, 19.1 ft. Record; N 12° E.
- W. Fir, now 16 ins. diam. brs. record; S 55° W, 48.8 ft.
- W. Fir, now 13 ins. diam. brs. record; N 75° W, 38.3 ft.

Mark new bearing tree "CS" "BT" and take measurement to center of tree at lower blaze:

- W. Fir 10 ins. diam. brs. S 45½° E, 46.0 ft.

Corner lies approx. 20 ft. west of gravel road.

October 25, 2012

H. Durkee

Scott Fein  
Deputy Jackson County  
Surveyor

P. – 66  
V. – 14°30'