

## FIRST RE-ESTABLISHMENT

### GCDB 700400

Section corner common to Sections 13 and 24, Township 39 South, Range 4 East, and Sections 18 and 19, Township 39 South, Range 5 East, W.M.  $V = 21\frac{1}{2}^\circ$

Found, the single remaining BT recorded by S. Truax in 1859, now a rotted Ponderosa Pine stump, 16-inch diameter, scribed "T39S R4E S13" and "BT" in exposed faces.

From the preceding evidence I set a 1 x 36-inch Galvanized iron pipe 6 inches deep in the center of a road, C.  $N82^\circ E$ , with  $2\frac{1}{2}$ -inch bronze disc marked:

Jackson County 1975	
T39S	
13	18
-----	
24	19
R4E R5E	

From which, the above original BT bears record,  $N39^\circ W$ , 27.06 feet to scribed lower face.

I marked new trees CS BT and took measurements to center of trees at lower blaze:

- Ponderosa Pine, 10-inch diameter bears  $N17^\circ E$ , 68.0 feet.
- Ponderosa Pine, 13-inch diameter bears  $S31^\circ E$ , 39.44 feet.
- Douglas Fir, 14-inch diameter bears  $S35^\circ W$ , 111.10 feet.
- Ponderosa Pine, 10-inch diameter bears  $N27^\circ W$ , 89.12 feet.

August 25, 1975  
B. Malotte  
R. Frost

Approved by: Edward McGinty  
County Surveyor

**SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT**

## SECOND RE-ESTABLISHMENT

GCDB 700400

Section corner common to Sections 13 and 24, Township 39 South, Range 4 East, and Sections 18 and 19, Township 39 South, Range 5 East, W.M.

Found 10 inches deep in center of cinder road, the 1-inch diameter galvanized iron pipe with 2½-inch diameter brass cap set on First Re-establishment in 1975, marked:

JACKSON COUNTY 1975

T39S	
13	18
-----	
24	19
R4E	R5E

Bearing trees marked on First Re-establishment in 1975, found and measured to center of tree at lower blaze:

- Ponderosa Pine, now 18-inch diameter with healed blazes bears Record: N 17° E, 68.0 feet.
- Ponderosa Pine, now a sawed stump 20-inch diameter bears Record: S 31° E, 39.44 feet.

Marked new tree "CS" "BT" and took measurements to center of tree at lower blaze:

- Lodge pole pine 5-inch diameter bears N 37½° W, 47.40 feet.
- Lodge pole pine 4-inch diameter bears S 29° E, 46.40 feet.

Corner lies in the center of cinder road, C. N 82° E.

Search coordinates: 42°10'15.1"  
122°17'14.9"

March 22, 2002  
H. Durkee  
T. Newcomb

Roger Roberts  
Jackson County Surveyor

P. -47  
V. - 18½°