

FIRST RE-ESTABLISHMENT

GCDB 700440

Quarter corner common to Sections 13, Township 39 South, Range 4 East and Section 18, Township 39 South, Range 5 East, W.M. $V = 20^\circ$

Found, $\frac{5}{8}$ -inch diameter re-steel rod with aluminum cap marked as reported on Survey No. 5550, dated 1973.

I replaced the above with a 1 x 36-inch Galvanized iron pipe set 30 inches in the ground with a 2½-inch bronze disc marked:

Jackson County 1975
T39S
¼S
13 | 18
R4E R5E

Original BTs recorded by S. Truax, in 1859, found as follows:

- Pine stump, 30-inch diameter, containing scribed "¼S BT" bears Record: S41°E, 12.54 feet to scribed face.
- A down Pine snag, the stump of which, 31-inch diameter containing partial scribed "B" bears Record: S55°W, 12.54 feet to scribed face.

I mounded stones around corner, deposited aluminum cap alongside, marked new trees CS BT and took measurements to center of trees at lower blaze:

- Pine, 12-inch diameter bears S48°E, 68.25 feet.
- Pine, 12-inch diameter bears S79½°W, 35.1 feet.

Corner lies at South edge of old road C. E-W and at corner of South and West bearing (down) fence lines.

August 26, 1975
B. Malotte
Ed Graham

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 700440

Quarter corner common to Section 13, township 39 South, Range 4 East, and Section 18, Township 39 South, Range 5 East, W.M.

Corner monument set on First Re-establishment in 1975, found bent over.

Replaced damaged monument with a 1 x 36-inch Galvanized iron pipe 30 inches in the ground with a 2½-inch diameter brass cap cemented in the top, marked:

JACKSON COUNTY SURVEYOR
T39S
R4E 13 • 18 R5E
2002

Original bearing trees recorded by Sewall Truax in 1859 found:

- Sawed rotted pine stump core 12-inch diameter, with opened blazes containing visible scribe marks "4S" and "BT" bears Record: S 41° E, 12.54 feet to face of lower blaze.
- Pine stump 24-inch diameter bears Record: S 55° W, 12.54 feet to face of weathered lower blaze.

Bearing trees recorded on First Re-establishment in 1975, found and measured to center of tree at lower blaze:

- Ponderosa Pine now 16-inch diameter with healed blazes bears Record: S79½°W, 35.1 feet.
- Ponderosa Pine now 18-inch diameter with healed blazes bears Record: S48°E, 68.25 feet.

Corner lies near northerly edge of large meadow. Fences recorded in 1975 now gone.

May 6, 2002

H. Durkee

T. Newcomb

Roger R. Roberts

Jackson County Surveyor

P. - 85

V. - 17½